

OIL ANALYSIS REPORT

Sample Rating Trend



CO 101 (S/N S0037DFMPTHBA3)

Refrigeration Compressor

FRICK COMPRESSOR OIL #3 (--- GAL)

Fluid Compressor

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


		эг2006 Mar20	109 Sep2011 Sep2013	Oct2015 Aug2017 Feb2020	Mar2022	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0903049	WC0847573	WC0789728
Sample Date		Client Info		01 Feb 2024	19 Aug 2023	25 Feb 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>8	0	7	<1
Chromium	ppm	ASTM D5185m	>2	0	0	0
Nickel	ppm	ASTM D5185m		<1	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>3	<1	0	0
Lead	ppm	ASTM D5185m	>2	0	0	0
Copper	ppm	ASTM D5185m	>8	0	0	0
Tin	ppm	ASTM D5185m	>4	<1	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		<1	3	<1
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	0	0
Magnesium	ppm	ASTM D5185m		<1	<1	0
Calcium	ppm	ASTM D5185m		1	0	0
Phosphorus	ppm	ASTM D5185m		0	1	0
Zinc	ppm	ASTM D5185m		0	2	0
Sulfur	ppm	ASTM D5185m		13	7	36
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	<1	<1	<1
Sodium	ppm	ASTM D5185m		<1	0	<1
Potassium	ppm	ASTM D5185m	>20	<1	<1	0
Water	%	ASTM D6304	>0.01	0.007	0.003	0.006
ppm Water	ppm	ASTM D6304	>100	70	26.2	68.8
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	^ 79612	<u> </u>	49637
Particles >6µm		ASTM D7647	>2500	15467	<u>▲</u> 76027	<u></u> ∧ 7887
Particles >14µm		ASTM D7647	>320	56	<u> </u>	86
Particles >21µm		ASTM D7647	>80	4	65	12
Particles >38µm		ASTM D7647	>20	0	0	2
Particles >71μm		ASTM D7647	>4	0	0	0
Oil Cleanliness		ISO 4406 (c)	>20/18/15	<u>23/21/13</u>	2 5/23/17	△ 23/20/14
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974		0.015	0.013	0.014





OIL ANALYSIS REPORT
















Laboratory Sample No. Lab Number **Unique Number** : 10896732

: WC0903049 : 06098502

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received

: 23 Feb 2024 **Tested** : 26 Feb 2024

Diagnosed : 26 Feb 2024 - Don Baldridge **BRAUM'S ICE CREAM PLANT**

PO BOX 725 TUTTLE, OK US 73089

Test Package: IND 2 (Additional Tests: PrtCount) Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

Contact: SCOTTY SCOTT sscott@braums.com;maintenanceoffice@braums.com T: (405)381-4427

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (405)381-2051 Contact/Location: SCOTTY SCOTT - BRATUTOK