


# **OIL ANALYSIS REPORT**



OKLAHOMA/3/EG - TRUCK-OFF-HWY-HEAVY HAUL Machine Id 69.02 [OKLAHOMA^3^EG - TRUCK-OFF-HWY-HEAVY HAUL] Component Differential

**MOBIL SHC 629 (--- GAL)** 



Sample Rating Trend





## DIAGNOSIS

### Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the


## **Fluid Condition**

The condition of the oil is acceptable for the time in service.


·-/		un2015 Fe	b2017 Jul2018 Ju	n2019 Aug2020 Apr2022	Aug2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0886938	WC0834068	WC0778282
Sample Date		Client Info		31 Jan 2024	05 Aug 2023	28 Feb 2023
Machine Age	hrs	Client Info		23455	22584	21769
Oil Age	hrs	Client Info		23455	22584	21769
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATIO	Ν	method	limit/base	current	history1	history2
Water		WC Method	>.2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>500	13	12	10
Chromium	ppm	ASTM D5185m	>3	0	<1	<1
Nickel	ppm	ASTM D5185m	>3	0	<1	<1
Titanium	ppm	ASTM D5185m	>2	0	<1	<1
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>30	0	2	1
Lead	ppm	ASTM D5185m	>13	0	<1	0
Copper	ppm	ASTM D5185m		3	2	1
Tin	ppm	ASTM D5185m	>5	0	<1	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
	ррпп		1: 1: 0			
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		10	13	12
Barium	ppm	ASTM D5185m		0	2	0
Molybdenum	ppm	ASTM D5185m		2	3	3
Manganese	ppm	ASTM D5185m		0	<1	<1
Magnesium	ppm	ASTM D5185m		25	31	29
Calcium	ppm	ASTM D5185m		2597	2887	2859
Phosphorus	ppm	ASTM D5185m		921	1006	972
Zinc	ppm	ASTM D5185m		1043	1185	1146
Sulfur	ppm	ASTM D5185m		6911	9719	8931
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>100	10	10	8
Sodium	ppm	ASTM D5185m		3	0	4
Potassium	ppm	ASTM D5185m	>20	0	1	0
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
21:20\ Pay: 1	Sualai	visual		NLG	INEG	





# **OIL ANALYSIS REPORT**



FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	142.8	175	176	178
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image











Laboratory Sample No.

: WC0886938 Lab Number : 06098773

Unique Number : 10897003 Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 23 Feb 2024

**Tested** : 26 Feb 2024 Diagnosed : 26 Feb 2024 - Don Baldridge

SHERWOOD CONSTRUCTION CO INC 3219 WEST MAY ST

WICHITA, KS US 67213

Contact: DOUG KING doug.king@sherwood.net

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (316)617-3161 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: x: