


# **OIL ANALYSIS REPORT**

## Sample Rating Trend



NORMAL



# TOLE\_U2 TOLE\_U2\_P2

**Drive End Pump** 

**ROYAL PURPLE SYNFILM GT 32 (2 QTS)** 

#### DIAGNOSIS

## Recommendation

Resample at the next service interval to monitor.

#### Moor

All component wear rates are normal.

### Contamination

The water content is negligible. There is no indication of any contamination in the oil.

## **Fluid Condition**


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


		flar2020 Sep2	020 Mar2021 Sep2021	Mar2022 Sep2022 Mar2023 Sep	2023 Feb 2024	
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		RP0025886	RP0034037	RP0026196
Sample Date		Client Info		21 Feb 2024	16 Nov 2023	25 Sep 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>90	0	0	0
Chromium	ppm	ASTM D5185m	>5	<1	0	0
Nickel	ppm	ASTM D5185m	>5	0	<1	<1
Titanium	ppm	ASTM D5185m	>3	0	0	0
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m	>7	0	<1	<1
Lead	ppm	ASTM D5185m	>12	0	<1	<1
Copper	ppm	ASTM D5185m	>30	0	0	0
Tin	ppm	ASTM D5185m	>9	0	0	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	0	0
Magnesium	ppm	ASTM D5185m		86	87	75
Calcium	ppm	ASTM D5185m		4	4	4
Phosphorus	ppm	ASTM D5185m		1	4	2
Zinc	ppm	ASTM D5185m		0	0	6
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>60	0	<1	<1
Sodium	ppm	ASTM D5185m		0	<1	1
Potassium	ppm	ASTM D5185m	>20	0	<1	0
Water	%	ASTM D6304		0.011	0.025	0.027
ppm Water	ppm	ASTM D6304	>1000	115	257	273.8
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.466	0.428	0.466
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>.1	NEG	NEG	NEG


NEG SWEGitted By: JONESLAZEY



## **OIL ANALYSIS REPORT**













## **GRAPHS**













Certificate L2367

Laboratory Sample No.

Lab Number : 06101699 Unique Number: 10899929 Test Package : PLANT

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : RP0025886 Received

**Tested** Diagnosed

: 29 Feb 2024 : 29 Feb 2024 - Don Baldridge

: 27 Feb 2024

**ENERGY TRANSFER - TOLEDO** 2549 BROWN ROAD

OREGON, OH US 43616

T: (419)389-7403

Contact: DARREN GRANT

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: