

OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id WC0904986

Component Hydraulic System Fluid {not provided} (--- GAL)

DIAGNOSIS

A Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

Appearance is hazy. There is a high amount of silt (particulates < 6 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0904986		
Sample Date		Client Info		14 Mar 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	4		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m	>10	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>10	0		
Lead	ppm	ASTM D5185m	>10	0		
Copper	ppm	ASTM D5185m	>75	2		
Tin	ppm	ASTM D5185m	>10	- <1		
Vanadium	ppm	ASTM D5185m	210	0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		4		
Manganese	ppm	ASTM D5185m		- <1		
Magnesium		ASTM D5185m		8		
Calcium	ppm	ASTM D5185m		905		
	ppm					
Phosphorus	ppm	ASTM D5185m		565		
Zinc	ppm	ASTM D5185m		620		
Sulfur	ppm	ASTM D5185m		2177		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	8		
Sodium	ppm	ASTM D5185m		1		
Potassium	ppm	ASTM D5185m	>20	0		
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
FLUID CLEANLIN Particles >4µm	ESS	method ASTM D7647	limit/base >5000	▲ 39315	history1	history2
	ESS		>5000			
Particles >4µm	ESS	ASTM D7647	>5000	▲ 39315		
Particles >4μm Particles >6μm	ESS	ASTM D7647 ASTM D7647	>5000 >1300 >160	▲ 39315 1058		
Particles >4μm Particles >6μm Particles >14μm	ESS	ASTM D7647 ASTM D7647 ASTM D7647	>5000 >1300 >160	▲ 39315 1058 65		
Particles >4µm Particles >6µm Particles >14µm Particles >21µm	ESS	ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647	>5000 >1300 >160 >40 >10	 39315 1058 65 14 		
Particles >4µm Particles >6µm Particles >14µm Particles >21µm Particles >38µm	ESS	ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647	>5000 >1300 >160 >40 >10	 39315 1058 65 14 0 		
Particles >4µm Particles >6µm Particles >14µm Particles >21µm Particles >38µm Particles >71µm		ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647	>5000 >1300 >160 >40 >10 >3	 39315 1058 65 14 0 0 	 	
Particles >4µm Particles >6µm Particles >14µm Particles >21µm Particles >38µm Particles >71µm Oil Cleanliness		ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647 ISO 4406 (c)	>5000 >1300 >160 >40 >10 >3 >19/17/14	 39315 1058 65 14 0 0 22/17/13 		

Report Id: EJLFAR [WUSCAR] 06125604 (Generated: 03/26/2024 17:44:49) Rev: 1

Contact/Location: Service Manager - EJLFAR



OIL ANALYSIS REPORT



Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

4/24

Mar1

EJ LUMBER

US 22460

FARNHAM, VA

7082 HISTROY LAND HWY

Contact: Service Manager

14

Acid Number

21µ

history1

history

history1

no image

no image

current

NONE

NONE

NONE

NONE

LIGHT

NONE

HAZY

NEG

NEG

40.2

NORML

current

current

Particle Count

480

120

31

0.40

0.20

0.00

4/74

Marl

history2

history2

history2

no image

no imade

4406

:1999 Cle

14