

OIL ANALYSIS REPORT

Area {UNASSIGNED} P-1301B PUMP (S/N R11Q6290AX-01) Component Pump

Fluid **ROYAL PURPLE SYNFILM GT 150 (5 GAL)**

Recommendation

Resample at the next service interval to monitor.

Wear


All component wear rates are normal.

Contamination

Fuel content negligible. There is no indication of any contamination in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.




Sample Rating Trend

NORMAL

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		RP0043770	RP0042964	RP0042464
Sample Date		Client Info		22 Mar 2024	01 Mar 2024	12 Feb 2024
Machine Age	hrs	Client Info		73916	81825	73854
Oil Age	hrs	Client Info		9581	18503	9519
Oil Changed		Client Info		Not Changd	Not Changd	Not Changd
Sample Status				NORMAL	ATTENTION	ATTENTION
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>90	5	10	9
Chromium	ppm	ASTM D5185m	>5	<1	<1	0
Nickel	ppm	ASTM D5185m	>5	<1	<1	<1
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m		1	2	<1
Lead	ppm	ASTM D5185m	>12	0	<1	2
Copper	ppm		>30	0	11	12
Tin	ppm	ASTM D5185m	>9	0	<1	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	<1
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		9	43	43
Manganese	ppm	ASTM D5185m		0	0	<1
Magnesium	ppm	ASTM D5185m		320	1162	1119
Calcium	ppm	ASTM D5185m		299	1168	1175
Phosphorus	ppm	ASTM D5185m		254	1011	1096
Zinc	ppm	ASTM D5185m		309	1259	1252
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>60	3	7	6
Sodium	ppm	ASTM D5185m		<1	0	3
Potassium	ppm	ASTM D5185m	>20	<1	1	<1
Water	%	ASTM D6304	>.1	0.027	0.002	0.081
ppm Water	ppm	ASTM D6304	>1000	270	25	810
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.745	1.89	1.78
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NESubmitte	d ByjjEeam Sur
						Page 1 of 2




OIL ANALYSIS REPORT







GRAPHS









: WearCheck USA - 501 Madison Ave., Cary, NC 27513

Received


Diagnosed

Tested

: 29 Mar 2024

: 01 Apr 2024

: 03 Apr 2024 - Jonathan Hester



TEAM SUR S.A.S.

BOGOTA, CO Contact: Team Sur jconde@teamsur.com T: (300)740-0654 F:



Test Package : IND 2 Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: TEABOG [WUSCAR] 06133478 (Generated: 04/03/2024 16:07:08) Rev: 1

Laboratory

Sample No.

Lab Number : 06133478

Unique Number : 10952943

: RP0043770