

# **OIL ANALYSIS REPORT**

Sulfur

**Emulsified Water** 

ppm

ASTM D5185m

\*Visual

scalar

scalar \*Visual

SAMPLE INFORMATION method

#### Sample Rating Trend

NORMAL



# TOWER 7P (S/N 002145823-1-1)

Component

**Right Gearbox** 

SHELL MORLINA S4 B 220 (18 GAL)

#### DIAGNOSIS

#### Recommendation

Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

#### Contamination

There is no indication of any contamination in the oil

### **Fluid Condition**

The condition of the oil is acceptable for the time in service.

					111010171	, _
Sample Number		Client Info		TO60002405	TO60001380	TO60001132
Sample Date		Client Info		25 Mar 2024	04 Jan 2024	03 Aug 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184		11	15	14
Iron	ppm	ASTM D5185m	>200	0	0	0
Chromium	ppm	ASTM D5185m	>15	0	0	0
Nickel	ppm	ASTM D5185m	>15	0	0	0
Titanium	ppm	ASTM D5185m		0	0	<1
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	0	0	0
Lead	ppm	ASTM D5185m	>100	0	0	0
Copper	ppm	ASTM D5185m	>200	0	0	<1
Tin	ppm	ASTM D5185m	>25	0	<1	0
Vanadium	ppm	ASTM D5185m		0	0	<1
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		3	4	2
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m		0	0	2
Calcium	ppm	ASTM D5185m		0	0	0
Phosphorus	ppm	ASTM D5185m		287	312	310
Zinc	ppm	ASTM D5185m		0	0	3

CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	<1	2	2
Sodium	ppm	ASTM D5185m		0	0	<1
Potassium	ppm	ASTM D5185m	>20	0	0	2
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	LIGHT	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML

>0.2

769

NEG

**NEG** 

661

NEG

NEG

mitted By: CLAY OSTERHOUT

797



## **OIL ANALYSIS REPORT**







Laboratory Sample No.

: TO60002405 Lab Number : 06133658

Unique Number : 10953123

Received : 29 Mar 2024 **Tested** 

: 03 Apr 2024 Diagnosed Test Package: IND 2 (Additional Tests: KV100, PQ, VI)

: 03 Apr 2024 - Sean Felton

ROGERS, AR US 72756 Contact: CLAY OSTERHOUT

1700 N 13TH ST

clay.osterhout@clorox.com T:

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: GLAROG [WUSCAR] 06133658 (Generated: 04/03/2024 12:50:15) Rev: 1

F: