

FUEL REPORT

I

Bottom

Machine Id

Westchester def 10 doosan lightowers 495826UIADG79 Diesel Fuel

Fluid No.2 DIESEL FUEL (ULTRALOW SULPHUR) (--- GAL)

DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample.

Corrosion


All metal levels are normal indicating no corrosion in the system.

Contaminants

There is no indication of any contamination in the fuel.

Fuel Condition

The condition of the fuel is acceptable for the time in service.




SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number Sample Date Machine Age Sample Status	hrs	Client Info Client Info Client Info		WC0878264 20 Mar 2024 40 NORMAL	WC0799895 02 May 2023 33 NORMAL	WC0651394 04 May 2022 27 NORMAL
SULFUR CONTEN	NT	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185m	10	4	0	2
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	<1.0	<1	2	0
Sodium	ppm	ASTM D5185m	<0.1	1	0	<1
Potassium	ppm	ASTM D5185m	<0.1	0	0	0
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185m	<0.1	0	2	0
Nickel	ppm	ASTM D5185m	<0.1	0	0	0
Lead	ppm	ASTM D5185m	<0.1	0	0	0
Vanadium	ppm	ASTM D5185m	<0.1	0	0	0
Iron	ppm	ASTM D5185m	<0.1	0	0	0
Calcium	ppm	ASTM D5185m	<0.1	0	0	0
Magnesium	ppm	ASTM D5185m	<0.1	0	0	0
Phosphorus	ppm	ASTM D5185m	<0.1	0	1	0
Zinc	ppm	ASTM D5185m	<0.1	0	0	0
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color				a.		





FUEL REPORT

GRAPHS



Report Id: GENNEW [WUSCAR] 06135366 (Generated: 04/05/2024 16:03:50) Rev: 1

Contact/Location: JOE SAYEGH - GENNEW