

OIL ANALYSIS REPORT

Sample Rating Trend



DIRT



Machine Id

VOLVO 315217

Left Final Drive

VOLVO SUPER GEAR OIL 75W-80-GO102 (

DIAGNOSIS

Recommendation

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.

Metal levels are typical for a new component breaking in.

Contamination

Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress.


Fluid Condition

The oil viscosity is higher than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

(GAL)				Mar2024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		ML0000609		
Sample Date		Client Info		29 Mar 2024		
Machine Age	hrs	Client Info		495		
Oil Age	hrs	Client Info		495		
Oil Changed		Client Info		Changed		
Sample Status				ABNORMAL		
CONTAMINATIO	V	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>500	524		
Chromium	ppm	ASTM D5185m	>10	12		
Nickel	ppm	ASTM D5185m	>10	<1		
Titanium	ppm	ASTM D5185m		4		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	<u>25</u>		
Lead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m	>50	1		
Tin	ppm	ASTM D5185m	>10	27		
Vanadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		8		
Magnesium	ppm	ASTM D5185m		3		
Calcium	ppm	ASTM D5185m		<u> </u>		
Phosphorus	ppm	ASTM D5185m		212		
Zinc	ppm	ASTM D5185m		19		
Sulfur	ppm	ASTM D5185m		15743		
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	157		
Sodium	ppm	ASTM D5185m		8		
Potassium	ppm	ASTM D5185m	>20	7		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	MODER		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	MODER		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.2	NEG		
Free Water	scalar	*Visual		NEG		
1:00:14) Rev: 1				Submit	ted By: Service	- Alex Anderson



OIL ANALYSIS REPORT





Certificate 12367

Laboratory Sample No. : ML0000609 Lab Number : 06138183 Unique Number : 10962991 Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 03 Apr 2024

Tested : 04 Apr 2024 Diagnosed : 06 Apr 2024 - Don Baldridge

MCCLUNG-LOGAN EQUIPMENT CO - RICHMOND 1345 MOUNTAIN ROAD

GLEN ALLEN, VA US 23060

Contact: Alex Anderson aanderson@mcclung-logan.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (804)266-1611

Report Id: VOLVO8882 [WUSCAR] 06138183 (Generated: 04/06/2024 11:00:14) Rev: 1