

OIL ANALYSIS REPORT






Area KANSAS/44 20.307L [KANSAS^44]

Component

Left Final Drive

MOBIL MOBILTRANS HD 50 (1 GAL)





Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The condition of the oil is acceptable for the time in service.


SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0918126	WC0862577	WC0862603
Sample Date		Client Info		28 Mar 2024	19 Jan 2024	05 Dec 2023
Machine Age	hrs	Client Info		1539	1819	1797
Oil Age	hrs	Client Info		0	22	861
Oil Changed		Client Info		Not Changd	N/A	Changed
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATION	٧	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>800	68	25	140
Chromium	ppm	ASTM D5185m	>10	1	<1	2
Nickel	ppm	ASTM D5185m	>5	<1	<1	0
Titanium	ppm	ASTM D5185m	>15	<1	0	0
Silver	ppm	ASTM D5185m	>2	<1	0	0
Aluminum	ppm	ASTM D5185m	>75	3	<1	<1
Lead	ppm	ASTM D5185m	>10	1	<1	0
Copper	ppm	ASTM D5185m	>75	<1	<1	0
Tin	ppm	ASTM D5185m	>8	1	<1	0
Vanadium	ppm	ASTM D5185m		<1	<1	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		3	0	1
Barium	ppm	ASTM D5185m		0	0	1
Molybdenum	ppm	ASTM D5185m		<1	0	0
Manganese	ppm	ASTM D5185m		1	0	<1
Magnesium	ppm	ASTM D5185m		12	12	14
Calcium	ppm	ASTM D5185m		3149	3038	3074
Phosphorus	ppm	ASTM D5185m		1104	1078	1009
Zinc	ppm	ASTM D5185m		1285	1255	1269
Sulfur	ppm	ASTM D5185m		7994	6649	7175
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>400	12	8	10
Sodium	ppm	ASTM D5185m		<1	2	<1
Potassium	ppm	ASTM D5185m	>20	2	0	0
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
A	scalar	*Visual	NORML	NORML	NORML	NORML
Appearance						
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
	scalar scalar	*Visual	NORML >0.2	NORML NEG	NORML NEG	NORML NEG
Odor						





OIL ANALYSIS REPORT



FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	195	180	193	167
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image
CDADHC						









Certificate 12367

Laboratory

Sample No. : WC0918126 Lab Number : 06138913 Unique Number : 10963721

Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 04 Apr 2024

Tested : 05 Apr 2024 : 05 Apr 2024 - Wes Davis Diagnosed

SHERWOOD CONSTRUCTION CO INC 3219 WEST MAY ST WICHITA, KS US 67213

Contact: RANDY ROBERTS randy.roberts@sherwood.net T: (316)943-6491

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: SHEWIC [WUSCAR] 06138913 (Generated: 04/09/2024 11:24:05) Rev: 1

F: x: