


# **OIL ANALYSIS REPORT**

# **PALLUBE 32 [2518] SULLIVAN PALATEK 22HE003313 - CITY OF MT VIEW**

Component Compressor





## DIAGNOSIS

## Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the


## **Fluid Condition**

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		UCS06141493	UCS05818925	UCS05804087
Sample Date		Client Info		30 Mar 2024	29 Mar 2023	17 Mar 2023
Machine Age	hrs	Client Info		12185	480	3623
Oil Age	hrs	Client Info		0	480	3623
Oil Changed		Client Info		Changed	Changed	Not Changd
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	0	2	3
Chromium	ppm	ASTM D5185m	>10	0	0	<1
Nickel	ppm	ASTM D5185m		0	0	<1
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	0	0	1
Lead	ppm	ASTM D5185m	>25	0	0	0
Copper	ppm	ASTM D5185m	>50	0	1	<1
Tin	ppm	ASTM D5185m	>15	<1	<1	<1
Vanadium	ppm	ASTM D5185m		0	0	<1
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	1	0	0	0
Barium	ppm	ASTM D5185m	730	480	358	341
Molybdenum	ppm	ASTM D5185m	0	0	<1	<1
Manganese	ppm	ASTM D5185m	0.0	0	<1	<1
Magnesium	ppm	ASTM D5185m	0	0	2	<1
Calcium	ppm	ASTM D5185m	0	0	4	5
Phosphorus	ppm	ASTM D5185m	0	0	241	114
Zinc	ppm	ASTM D5185m	0	0	14	14
Sulfur	ppm	ASTM D5185m	590	663	1001	693
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	<1	1	1
Sodium	ppm	ASTM D5185m		50	89	116
Potassium	ppm	ASTM D5185m	>20	1	4	4
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.14	0.087	0.20	0.16

# **Sullivan**

## **OIL ANALYSIS REPORT**



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	LIGHT	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	LIGHT
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	LIGHT	LIGHT
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
<b>Emulsified Water</b>	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	42.8	43.9	41.5	40.9
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color						



: 08 Apr 2024

: 09 Apr 2024

: 10 Apr 2024 - Sean Felton





Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : UCS06141493 Lab Number : 06141493

Unique Number : 10966301

**Bottom** 

Received

**Tested** Diagnosed

Test Package : IND 2

Certificate 12367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

US 95112 Contact: EDNA IADIANO

D & D COMPRESSOR INC

edna@danddcompressor.com T: (408)947-0491

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) SAN JOSE, CA