

OIL ANALYSIS REPORT









Machine Id VOLVO A45G Branch Civil A45G 353356

Component
Center Axle

VOLVO SUPER GEAR OIL 75W-80-GO102 (7 GAL)

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The condition of the oil is acceptable for the time in service.

_ 75W-80-GO102 (/ GAL)			Apr2024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		ML0000337		
Sample Date		Client Info		01 Apr 2024		
Machine Age	hrs	Client Info		2261		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
CONTAMINATION	٧	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>900	71		
Chromium	ppm	ASTM D5185m	>20	1		
Nickel	ppm	ASTM D5185m	>10	3		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>30	1		
_ead	ppm	ASTM D5185m	>50	<1		
Copper	ppm	ASTM D5185m	>150	61		
Γin	ppm	ASTM D5185m	>20	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		78		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		1		
Magnesium	ppm	ASTM D5185m		10		
Calcium	ppm	ASTM D5185m		3277		
Phosphorus	ppm	ASTM D5185m		1206		
Zinc	ppm	ASTM D5185m		1339		
Sulfur	ppm	ASTM D5185m		6262		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	17		
Sodium	ppm	ASTM D5185m		8		
Potassium	ppm	ASTM D5185m	>20	0		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	LIGHT		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.2	NEG		
ree Water	scalar	*Visual		NEG		





OIL ANALYSIS REPORT






Ferrous Alloys









Certificate 12367

Laboratory

Sample No. : ML0000337 Lab Number : 06146186 Unique Number : 10976264

Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Tested

: 11 Apr 2024 : 12 Apr 2024 Diagnosed : 15 Apr 2024 - Don Baldridge

MCCLUNG-LOGAN EQUIPMENT CO - SALEM 2025 COOK DRIVE SALEM, VA

> US 24153 Contact: Zachary Asimakopoulous Zacharya@mcclung-logan.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: VOLVO9010 [WUSCAR] 06146186 (Generated: 04/15/2024 13:54:20) Rev: 2

Submitted By: Zachary Asimakopoulous

T:

F: