


FUEL REPORT

Sample Rating Trend



VIS DEBRIS



Machine Id
6623
Component
Diesel Fuel

No.2 DIESEL FUEL (ULTRALOW SULPHUR) (--- GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component.

Corrosion

All metal levels are normal indicating no corrosion in the system.

Contaminants

Moderate concentration of visible dirt/debris present in the fuel. The water content is negligible.


Fuel Condition

The condition of the fuel is acceptable for the time in service.


SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0893087	WC0526142	
Sample Date		Client Info		10 Feb 2024	22 Aug 2022	
Machine Age	hrs	Client Info		10565	9039	
Sample Status				ABNORMAL	NORMAL	
PHYSICAL PROP	ERTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	3.0	2.76	2.46	
SULFUR CONTER	VΤ	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185m	10	18	13	
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	<1.0	0	<1	
Sodium	ppm	ASTM D5185m	< 0.1	<1	0	
Potassium	ppm	ASTM D5185m	<0.1	0	0	
Water	%	ASTM D6304	< 0.05	0.004	0.004	
ppm Water	ppm	ASTM D6304	< 500	49	48.9	
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185m	< 0.1	0	<1	
Nickel	ppm	ASTM D5185m	<0.1	0	0	
Lead	ppm	ASTM D5185m	< 0.1	0	0	
Vanadium	ppm	ASTM D5185m	<0.1	0	0	
Iron	ppm	ASTM D5185m	< 0.1	0	0	
Calcium	ppm	ASTM D5185m	<0.1	3	2	
Magnesium	ppm	ASTM D5185m	<0.1	0	0	
Phosphorus	ppm	ASTM D5185m	<0.1	0	4	
Zinc	ppm	ASTM D5185m	<0.1	0	0	
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color						no image
Bottom						no image



FUEL REPORT









Certificate 12367

Laboratory

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No. : WC0893087 Lab Number : 06149220 $\textbf{Unique Number} \quad : 10979298$

Test Package : CONST (Additional Tests: KF)

Received **Tested** Diagnosed

: 15 Apr 2024 : 18 Apr 2024

: 18 Apr 2024 - Jonathan Hester

BUCKNER - WILLIS 18123 HWY 75 NORTH WILLIS, TX US 77378

Contact: JOHN HAWKINS johnh@bucknercompanies.com T:

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: BUCWILTX [WUSCAR] 06149220 (Generated: 04/18/2024 11:30:35) Rev: 1

F: