
Sample Rating Trend


SAPP BROS. PETROLEUM

PROBLEM SUMMARY



Machine Id BL-43 Component East Gearbox Fluid PETRO CANADA SYNDURO SHB ISO 220 (2 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS							
Sample Status			SEVERE	SEVERE	ABNORMAL		
Particles >4µm	ASTM D7647	>20000	<u> </u>	2 97611	▲ 366322		
Particles >6µm	ASTM D7647	>5000	66678	4 5502	▲ 326832		
Oil Cleanliness	ISO 4406 (c)	>21/19/16	4 24/23/15	▲ 25/23/15	▲ 26/26/24		

Customer Id: MONHAL Sample No.: SBP0000907 Lab Number: 06151077 Test Package: PLANT



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action Change Filter	Status	Date	Done By	Description We recommend you service the filters on this component.			
Resample			?	Resample in 30-45 days to monitor this situation.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Seals			?	Check seals and/or filters for points of contaminant entry.			

HISTORICAL DIAGNOSIS



12 Dec 2023 Diag: Wes Davis

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The water content is negligible. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



DIRT

31 Aug 2023 Diag: Don Baldridge

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.Gear wear is indicated. All other component wear rates are normal. There is a high amount of particulates present in the oil. Elemental level of silicon (Si) above normal indicating ingress of dirt/seal material. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.





21 May 2023 Diag: Don Baldridge


We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.Gear wear is indicated. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



Component East Gearbox Fluid PETRO CANADA SYNDURO SHB ISO 220 (2 GAL)

DIAGNOSIS

Machine Id BL-43

Recommendation

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil. The water content is negligible.

Fluid Condition


The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		SBP0000907	SBP0001139	SBP0001825
Sample Date		Client Info		08 Apr 2024	12 Dec 2023	31 Aug 2023
Machine Age		Client Info		0	0	0
Oil Age		Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184		53	41	104
Iron	ppm	ASTM D5185m	>200	71	46	1 43
Chromium	ppm	ASTM D5185m	>15	<1	<1	2
Nickel	ppm	ASTM D5185m	>15	2	<1	5
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	1	0	2
Lead	ppm	ASTM D5185m	>100	0	0	0
Copper	ppm	ASTM D5185m	>200	3	<1	2
Tin	ppm	ASTM D5185m		<1	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m	5.0	0	0	7
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		2	<1	<1
Magnesium	ppm	ASTM D5185m	5.0	2	0	5
Calcium	ppm	ASTM D5185m	5.0	3	0	0
Phosphorus	ppm	ASTM D5185m	100	135	119	311
Zinc	ppm	ASTM D5185m	5.0	<1	2	128
Sulfur	ppm	ASTM D5185m	1900	2652	2094	746
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	13	6	A 23
Sodium	ppm	ASTM D5185m		2	0	0
Potassium	ppm	ASTM D5185m	>20	2	0	1
Water	%	ASTM D6304	>0.2	0.00	0.003	0.003
ppm Water	ppm	ASTM D6304	>2000	0	34	38.2
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	153609	2 97611	▲ 366322
Particles >6µm		ASTM D7647	>5000	66678	▲ 45502	▲ 326832
Particles >14µm		ASTM D7647	>640	233	250	112107
Particles >21µm		ASTM D7647	>160	31	43	<u> </u>
Particles >38µm		ASTM D7647	>40	1	1	3
Particles >71µm		ASTM D7647	>10	1	0	0
Oil Cleanliness		ISO 4406 (c)	>21/19/16	4 24/23/15	▲ 25/23/15	▲ 26/26/24
FLUID DEGRADA		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.3	0.44	0.39	0.64
9:34:31) Rev: 1	с о					THAN KUGLER


Report Id: MONHAL [WUSCAR] 06151077 (Generated: 04/19/2024 09:34:31) Rev: 1



OIL ANALYSIS REPORT



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	LIGHT	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	219	214	209	217
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color						
Bottom						



To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: MONHAL [WUSCAR] 06151077 (Generated: 04/19/2024 09:34:31) Rev: 1

Submitted By: NATHAN KUGLER

alana.wallace@monolith-corp.com

Т:

F: