


PROBLEM SUMMARY

Area COLD MILL/CM-3STD-1S Machine To SOUTH 3-STAND REWIND GEARBOX 1526-007-7540 Component

Gearbox

PETRO CANADA ENDURATEX EP 460 (100 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS Sample Status SEVERE SEVERE SEVERE Particles >4µm ASTM D7647 >20000 **137609 1**73703 ▲ 151035 Particles >6µm ASTM D7647 >5000 **4** 53153 ▲ 43353 ▲ 50998 **1**989 Particles >14µm ASTM D7647 >640 **1453** 1144 **Oil Cleanliness** ISO 4406 (c) >21/19/16 **424/23/18 2**5/23/17 ▲ 24/23/18


Customer Id: CONMUSAL Sample No.: KFS0004478 Lab Number: 06153062 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com



RECOMMENDED ACTIONS								
Action Change Filter	Status	Date	Done By	Description We recommend you service the filters on this component.				
			?					
Resample			?	Resample in 30-45 days to monitor this situation.				
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.				
Check Seals			?	Check seals and/or filters for points of contaminant entry.				

HISTORICAL DIAGNOSIS



29 Feb 2024 Diag: Wes Davis

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





05 Feb 2024 Diag: Wes Davis

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





05 Jan 2024 Diag: Wes Davis

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





OIL ANALYSIS REPORT

Area COLD MILL/CM-3STD-1S Machine to SOUTH 3-STAND REWIND GEARBOX 1526-007-7540 Component

Gearbox

PETRO CANADA ENDURATEX EP 460 (100 GAL)

DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

Wear


All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.




SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KFS0004478	KFS0004665	KFS0004672
Sample Date		Client Info		16 Apr 2024	29 Feb 2024	05 Feb 2024
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	SEVERE
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	9	7	4
Chromium	ppm	ASTM D5185m	>15	0	0	0
Nickel	ppm	ASTM D5185m	>15	<1	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	<1	0	0
Lead	ppm	ASTM D5185m	>100	<1	0	0
Copper	ppm	ASTM D5185m	>200	<1	0	0
Tin	ppm	ASTM D5185m	>25	<1	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	55	36	30	34
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	0	0	0	0
Manganese	ppm	ASTM D5185m	0	<1	0	0
Magnesium	ppm	ASTM D5185m	2	1	0	0
Calcium	ppm	ASTM D5185m	6	1	0	0
Phosphorus	ppm	ASTM D5185m	240	209	195	172
Zinc	ppm	ASTM D5185m	3	0	0	0
Sulfur	ppm	ASTM D5185m	10310	8735	7051	7149
CONTAMINANTS	S	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	8	8	7
Sodium	ppm	ASTM D5185m		2	0	<1
Potassium	ppm	ASTM D5185m		3	0	0
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	A 137609	▲ 173703	▲ 151035
Particles >6µm		ASTM D7647	>5000	4 53153	4 3353	▲ 50998
Particles >14µm		ASTM D7647	>640	<u> </u>	1144	1 989
Particles >21µm		ASTM D7647	>160	151	137	268
Particles >38µm		ASTM D7647	>40	1	1	1
Particles >71µm		ASTM D7647	>10	0	0	0
Oil Cleanliness		ISO 4406 (c)	>21/19/16	4 24/23/18	▲ 25/23/17	4/23/18
FLUID DEGRAD	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.5	0.53	0.60	0.47
-47-28) Rev: 1						


Report Id: CONMUSAL [WUSCAR] 06153062 (Generated: 04/19/2024 12:47:28) Rev: 1


Submitted By: COLD MILL - Josh Edwards Page 3 of 4




OIL ANALYSIS REPORT











VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	452	434	444	446
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color					e Seek -	
Bottom						





Report Id: CONMUSAL [WUSCAR] 06153062 (Generated: 04/19/2024 12:47:28) Rev: 1

Submitted By: COLD MILL - Josh Edwards

Page 4 of 4