

OIL ANALYSIS REPORT

Sample Rating Trend ISO

Machine Id **TOTE 112**

New (Unused) Oil

{not provided} (--- GAL)

DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample.


Contamination

There is a high amount of silt (particulates < 6 microns in size) present in the oil.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		TLC0001636		
Sample Date		Client Info		19 Apr 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>5	0		
Chromium	ppm	ASTM D5185m	>5	0		
Nickel	ppm	ASTM D5185m	>5	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m	>5	0		
Aluminum	ppm	ASTM D5185m	>5	<1		
Lead	ppm	ASTM D5185m	>5	0		
Copper	ppm	ASTM D5185m	>5	0		
Tin	ppm	ASTM D5185m	>5	<1		
Vanadium	ppm	ASTM D5185m	-	0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		103		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		45		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		199		
Calcium	ppm	ASTM D5185m		870		
Phosphorus	ppm	ASTM D5185m		479		
Zinc	ppm	ASTM D5185m		535		
Sulfur	ppm	ASTM D5185m		2528		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	6		
Sodium	ppm	ASTM D5185m		3		
Potassium	ppm	ASTM D5185m	>20	6		
Water	%	ASTM D6304		NEG		
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	<u> </u>		
Particles >6µm		ASTM D7647	>1300	973		
Particles >14μm		ASTM D7647	>160	35		
Particles >21µm		ASTM D7647	>40	11		
Particles >38µm		ASTM D7647	>10	1		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u>^</u> 21/17/12		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		1.12		



OIL ANALYSIS REPORT





Certificate 12367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : TLC0001636 Lab Number : 06160884

Unique Number: 10996307

Received : 25 Apr 2024 **Tested** Diagnosed

: 30 Apr 2024

: 30 Apr 2024 - Jonathan Hester Test Package: PLANT (Additional Tests: FT-IR, ICP-NewOil, KV100, VI) To discuss this sample report, contact Customer Service at 1-800-237-1369.

US 30354 Contact: MICHAEL JACKSON mjackson@supplypro1.com T: (470)991-1693

 st - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: MICHAEL JACKSON - SUPATLGA

SUPPLY PRO

ATLANTA, GA

115 EMPIRE WAY