

FUEL REPORT

HER SON [CONHER] 2011 KENWORTH T. Orba FZO-0919 Kentworth Tanque diesel

Diesel Fuel

Fluid No.2 DIESEL FUEL (ULTRALOW SULPHUR) (--- GAL)

DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample. We recommend you service the filters on this component if applicable. (Customer Sample Comment: Sample taken from right tank)

Corrosion


All metal levels are normal indicating no corrosion in the cooling system.

Contaminants

There is a high amount of silt (particulates < 14 microns in size) present in the fuel. The water content is negligible.

Fuel Condition

The condition of the fuel is acceptable for the time in service.




SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KL0014569		
Sample Date		Client Info		26 Apr 2024		
Machine Age	hrs	Client Info		0		
Sample Status				ABNORMAL		
PHYSICAL PROP	ERTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	3.0	2.5		
SULFUR CONTER	NT	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185m	10	0		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	<1.0	0		
Sodium	ppm	ASTM D5185m	<0.1	<1		
Potassium	ppm	ASTM D5185m	<0.1	0		
Water	%	ASTM D6304	<0.05	0.001		
ppm Water	ppm	ASTM D6304	<500	7		
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647		12612		
Particles >6µm		ASTM D7647	>640	🔺 1684		
Particles >14µm		ASTM D7647	>80	73		
Particles >21µm		ASTM D7647	>20	15		
Particles >38µm		ASTM D7647	>4	1		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>16/13	1 8/13		
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185m	<0.1	0		
Nickel	ppm	ASTM D5185m	<0.1	0		
Lead	ppm	ASTM D5185m	<0.1	0		
Vanadium	ppm	ASTM D5185m	<0.1	0		
Iron	ppm	ASTM D5185m	<0.1	0		
Calcium	ppm	ASTM D5185m	<0.1	<1		
Magnesium	ppm	ASTM D5185m	<0.1	0		
Phosphorus	ppm	ASTM D5185m	<0.1	0		
Zinc	ppm	ASTM D5185m	<0.1	0		
SAMPLE IMAGES	6	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image



FUEL REPORT

GRAPHS



Pensky-Martens Flash Point (°C)								
]							
	3+							
	5+							
temperature °C	ş.							
	2							
temp	2-							
	3+							
	3+							
		+						
	Apr26/24	Aprz 6/24						

CONOR Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No. : KL0014569 Received :09 May 2024 JUAREZ 348 Lab Number : 06174547 Tested : 13 May 2024 HERMOSILLO, Unique Number : 11020600 Diagnosed : 13 May 2024 - Angela Borella MX 83140 Test Package : MOB 2 (Additional Tests: KF, PrtCount) Contact: EDUARDO GARCIA Certificate 12367 To discuss this sample report, contact Customer Service at 1-800-237-1369. egarcia.comsa@gmail.com * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (526)622-1581 x:81 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: x:

Submitted By: EDUARDO GARCIA Page 2 of 2