


OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

FREIGHTLINER 1170

Rear Differential

CHEVRON DELO XDM SYNTHETIC 75W90 (--- LTR)

DIAGNOSIS

Recommendation

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

,						
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0733180		
Sample Date		Client Info		11 May 2024		
Machine Age	mls	Client Info		594574		
Oil Age	mls	Client Info		300000		
Oil Changed		Client Info		Changed		
Sample Status				ABNORMAL		
CONTAMINATION	V	method	limit/base	current	history1	history2
Water		WC Method	>.2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>500	353		
Chromium	ppm	ASTM D5185m	>10	3		
Nickel	ppm	ASTM D5185m	>10	0		
Titanium	ppm	ASTM D5185m		2		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	<u> </u>		
Lead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m	>100	2		
Tin	ppm	ASTM D5185m	>10	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		240		
Barium	ppm	ASTM D5185m		2		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		8		
Magnesium	ppm	ASTM D5185m		8		
Calcium	ppm	ASTM D5185m		27		
Phosphorus	ppm	ASTM D5185m		1214		
Zinc	ppm	ASTM D5185m		15		
Sulfur	ppm	ASTM D5185m		22741		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	<u></u> 111		
Sodium	ppm	ASTM D5185m		16		
Potassium	ppm	ASTM D5185m	>20	5		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		2.19		



OIL ANALYSIS REPORT







Certificate 12367

Laboratory Sample No.

: WC0733180 Lab Number : 06175674 Unique Number : 11021727

Test Package : MOB 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 10 May 2024

Tested : 13 May 2024 Diagnosed : 14 May 2024 - Don Baldridge

LYNDEN TRANSPORT - SPRUCE GROVE 27340 ACHESON RD, ACHESON INDUSTRIAL PARK ACHESON, AB **CA T7X 6B1**

Contact: Mathieu Carby mcarby@lynden.com

To discuss this sample report, contact Customer Service at 1-800-237-1369.

 st - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: LYNSPR [WUSCAR] 06175674 (Generated: 05/14/2024 17:00:02) Rev: 1

Contact/Location: Mathieu Carby - LYNSPR

T:

F: