


# **OIL ANALYSIS REPORT**



KANSAS/15/EG - EXCAVATOR 20.145L [KANSAS^15^EG - EXCAVATOR]

Rear Left Final Drive

MOBIL MOBILTRANS HD 50 (1 GAL)





### Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the


## **Fluid Condition**

The condition of the oil is acceptable for the time in service.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0918358	WC0901229	WC0833946
Sample Date		Client Info		01 May 2024	05 Mar 2024	11 Sep 2023
Machine Age	hrs	Client Info		0	6	6
Oil Age	hrs	Client Info		0	0	6
Oil Changed		Client Info		Not Changd	Not Changd	Not Changd
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATION	٧	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>800	59	59	13
Chromium	ppm	ASTM D5185m	>10	<1	<1	<1
Nickel	ppm	ASTM D5185m	>5	0	0	0
Titanium	ppm	ASTM D5185m	>15	<1	<1	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>75	6	7	5
Lead	ppm	ASTM D5185m	>10	<1	0	0
Copper	ppm	ASTM D5185m	>75	2	1	<1
Tin	ppm	ASTM D5185m	>8	<1	0	0
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		19	0	13
Molybdenum	ppm	ASTM D5185m		<1	0	0
Manganese	ppm	ASTM D5185m		1	1	<1
Magnesium	ppm	ASTM D5185m		17	1	19
Calcium	ppm	ASTM D5185m		3539	3540	3389
Phosphorus	ppm	ASTM D5185m		958	925	837
Zinc	ppm	ASTM D5185m		1100	1104	1066
Sulfur	ppm	ASTM D5185m		11257	12119	11426
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>400	40	39	16
Sodium	ppm	ASTM D5185m		2	5	4
Potassium	ppm	ASTM D5185m	>20	7	3	<1
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt		*Visual	NORML	NORML	NORML	NORML
	scalar	ViSuai	TACTUVE			
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Appearance Odor Emulsified Water						NORML NEG





## **OIL ANALYSIS REPORT**




FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	195	86.9	87.2	88.2
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image

## Ferrous Alloys











Certificate 12367

**Sample No.** : WC0918358 Lab Number : 06175914 Unique Number : 11021967 Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 10 May 2024

Tested : 13 May 2024 Diagnosed : 14 May 2024 - Sean Felton

SHERWOOD CONSTRUCTION CO INC 3219 WEST MAY ST

WICHITA, KS US 67213

Contact: RANDY ROBERTS randy.roberts@sherwood.net

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: F: x: