


OIL ANALYSIS REPORT

PALLUBE FG **PALATEK 19EE00078 - SALM PARTNERS**

Component Compressor





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the

Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		UCS06178879	UCS06032399	UCS05937320
Sample Date		Client Info		03 May 2024	03 Dec 2023	13 Aug 2023
Machine Age	hrs	Client Info		40763	37093	34487
Oil Age	hrs	Client Info		4000	2146	4000
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	<1	0	<1
Chromium	ppm	ASTM D5185m	>10	<1	0	<1
Nickel	ppm	ASTM D5185m		0	0	0
Titanium	ppm	ASTM D5185m		<1	0	<1
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	1	0	<1
Lead	ppm	ASTM D5185m	>25	0	0	<1
Copper	ppm	ASTM D5185m	>50	2	0	3
Tin	ppm	ASTM D5185m	>15	<1	0	<1
Vanadium	ppm	ASTM D5185m		<1	0	<1
Cadmium	ppm	ASTM D5185m		0	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	1	0	0	0
Barium	ppm	ASTM D5185m	730	0	0	0
Molybdenum	ppm	ASTM D5185m	0	0	0	0
Manganese	ppm	ASTM D5185m	0.0	0	0	<1
Magnesium	ppm	ASTM D5185m	0	0	0	6
Calcium	ppm	ASTM D5185m	0	3	0	22
Phosphorus	ppm	ASTM D5185m	0	429	478	348
Zinc	ppm	ASTM D5185m	0	16	34	57
Sulfur	ppm	ASTM D5185m	590	1080	1128	597
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	<1	0	<1
Sodium	ppm	ASTM D5185m		0	1	2
Potassium	ppm	ASTM D5185m	>20	1	<1	2
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.14	0.50	0.50	1.24

Sullivan

38

OIL ANALYSIS REPORT




VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
ELLID DDODED	TIEC	mathad	limit/booo	OLLEK O ID t	biotom (1	hiotom/O


FLUID PROPER	THES	method			riistory i	HISTORY
Visc @ 40°C	cSt	ASTM D445	42.8	42.76	42.3	44.3


SAMPLE IMAGES


Color


Bottom















Certificate 12367

Laboratory

Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : UCS06178879 Lab Number : 06178879

Unique Number : 11030205 Test Package : IND 2

Received : 14 May 2024 **Tested** Diagnosed

: 20 May 2024 : 20 May 2024 - Don Baldridge

1490 GRUBER RD GREEN BAY, WI US 54313 Contact: ROBIN robin@vpc-inc.com

T: (920)662-1113

F: (920)662-1116

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

VACUUM PUMP and COMPRESSOR