

## **OIL ANALYSIS REPORT**

## Area [185233-N2STV4W] **EXT 13** Gearbox Fluid MOBIL SHC 634 (3 GAL)

Parker

#### Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

### Wear


All component wear rates are normal.

#### Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

### Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.







Report Id: TREPAS [WUSCAR] 06180131 (Generated: 05/18/2024 14:28:04) Rev: 1

Contact/Location: DARRYL DRUM - TREPAS Page 1 of 2

ISO



491.52 122.88

<sup>■</sup> 30,720

number of particles (per 1

7,68

1.920 480

120

30

8

Ê 20

) sa 15k 10k

51 0

0.70

0.60 (B/HO) 0.50 Ê 0.40 - 문 0.30

0.20 Acid 0.10 0.00


520

400

380 Mav8/74

And R

# **OIL ANALYSIS REPORT**



Test Package : PLANT (Additional Tests: PrtFilter)

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. TRELLEBORG HEALTHCARE AND MEDICAL 3077 ROLLIE GATE DR PASO POBLES, CA US 93446 Contact: DARRYL DRUM DARRYL.DRUM@TRELLEBORG.COM T: (805)239-4284

no image

no image

no image

no image

no imade

no image

Report Id: TREPAS [WUSCAR] 06180131 (Generated: 05/18/2024 14:28:04) Rev: 1

Certificate 12367

Contact/Location: DARRYL DRUM - TREPAS

E: