

## **OIL ANALYSIS REPORT**

Sample Rating Trend



DIAGNOSIS

A Wear

Recommendation

Oil and filter change at the time of sampling has

been noted. We advise that you inspect for the

resample to monitor this condition. ( Customer

Sample Comment: End of life sample. Oil and filters

source(s) of wear. We recommend an early

Elemental level of silicon (Si) above normal.

The BN result indicates that there is suitable alkalinity remaining in the oil. The AN level is

got changed due to bad sample )

The tin level is abnormal.

acceptable for this fluid.

Contamination

Fluid Condition

## Machine Id Brent Run CAT 3 BRRM03BE

**Biogas Engine** 

CHEVRON HDAX 9500 GAS ENGINE OIL 40 (--- GAL)



WEAR



## **OIL ANALYSIS REPORT**



Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: EDLMON [WUSCAR] 06181520 (Generated: 05/20/2024 10:21:26) Rev: 1

Submitted By: Jim Cruz Page 2 of 2

Montrose, MI

T:

F:

US 48457-9141

Contact: Rob Stewart

**EDL NA Recips-Brent Run** 

Brent Run Power Station, 8383 Vienna Road

Rob.Stewart@energydevelopments.com

NEG NEG NEG 14.1 13.9 13.5 Lead (ppm) Feb1/24 Mar23/23 n71/73 Chromium (ppm) Seven Ah Mar23/7 1/1/2 eb1/24 300 Silicon (ppm) 1773/73 Mar23/7 Mav9/2 Base Number un21/23 Mav9/23 v22/23 Feb1/24 Vor2/24 Aar23/7:

LIGHT

NONE

NONE

NONE

NONE

NONE

NORML

NORML

NEG

NONE

NONE

NONE

NONE

NONE

NONE

NORML

NORML

NEG

NONE

NONE

NONE

NONE

NONE

NONE

NORML

NORML

NEG