

Sample Number

Sample Date

Machine Age

Oil Changed

Sample Status

CONTAMINATION

WEAR METALS

Oil Age

Water

Iron

Nickel

Silver

Lead

Tin

Copper

Vanadium

Cadmium

ppm

ppm

ASTM D5185m

ASTM D5185m

Titanium

Aluminum

Chromium

# Area **HER SON [CONHER]** LIU GONG Altarena - Retroexcavadora #1 SH

**Hydraulic System** 

Mexlub H-300 ISO 68 (170 LTR)

# DIAGNOSIS

### Recommendation

We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. ( Customer Sample Comment: Fluid: Mexlub H-300 ISO 68)

## A Wear

The iron level is severe. Bearing and/or bushing wear is indicated.

### Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

#### Fluid Condition

The oil viscosity is higher than normal. Confirm oil type. The AN level is acceptable for this fluid.



ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		<1		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		1		
Magnesium	ppm	ASTM D5185m		8		
Calcium	ppm	ASTM D5185m		1483		
Phosphorus	ppm	ASTM D5185m		646		
Zinc	ppm	ASTM D5185m		764		
Sulfur	ppm	ASTM D5185m		4699		

0

0

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	10		
Sodium	ppm	ASTM D5185m		7		
Potassium	ppm	ASTM D5185m	>20	0		

FLUID CLEANLINESS	method	limit/base	current	history1	history2
Particles >4µm	ASTM D7647		116060		
Particles >6µm	ASTM D7647	>1300	<u> </u>		
Particles >14µm	ASTM D7647	>160	72		
Particles >21µm	ASTM D7647	>40	6		
Particles >38µm	ASTM D7647	>10	0		
Particles >71µm	ASTM D7647	>3	0		
Oil Cleanliness	ISO 4406 (c)	>17/14	<b>A</b> 21/13		
FLUID DEGRADATION	method	limit/base	current	history1	history2

Acid Number (AN) mg KOH/g ASTM D8045 0.438


Submitted By: EDUARDO GARCIA

Page 1 of 2

Sample Rating Trend



# **OIL ANALYSIS REPORT**



NONE NONE \*Visual scalar \*Visual NONE NONE scalar NONE scalar \*Visual NONE scalar \*Visual NONE NONE \*Visual NONE NONE scalar NONE NONE scalar \*Visual scalar NORML \*Visual NORML \*Visual NORML NORML scalar \*Visual scalar >0.1 NEG scalar \*Visual NEG limit/base ASTM D445 94.55 no image no image no image no imade Particle Count 491.52 122,880 30 720 7.680 May9/24 4406 per 1 1,920 :1999 Cle 480 120 14 30 214 Acid Number (<sup>0.50</sup> (<sup>0</sup>/HOX) Ē 0.30 · 문 0.20 0.10 Acid 0.00 Mav9/24 : WearCheck USA - 501 Madison Ave., Cary, NC 27513 CONOR Received : 20 May 2024 JUAREZ 348 Tested : 29 May 2024 HERMOSILLO, Diagnosed : 29 May 2024 - Don Baldridge MX 83140 Contact: EDUARDO GARCIA

To discuss this sample report, contact Customer Service at 1-800-237-1369

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: CONHERKL [WUSCAR] 06184261 (Generated: 05/29/2024 09:29:59) Rev: 1

同說

Submitted By: EDUARDO GARCIA

egarcia.comsa@gmail.com

T: (526)622-1581 x:81

Page 2 of 2

F: x: