

# **OIL ANALYSIS REPORT**

Sample Rating Trend





# Machine Id MLU-1 Component Outboard Lube System

**ROYAL PURPLE SYNFILM GT 32 (--- GAL)** 

## Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

# Contamination

There is no indication of any contamination in the oil.


# **Fluid Condition**


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


		Apr2023	Aug2023	Nov2023 Feb2024	May2024	
SAMPLE INFORM	1ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		RP0036039	RP0036127	RP0036174
Sample Date		Client Info		23 May 2024	19 Feb 2024	18 Nov 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	<1	0	0
Chromium	ppm	ASTM D5185m	>20	<1	<1	0
Nickel	ppm	ASTM D5185m	>20	<1	0	<1
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m		1	0	0
Aluminum	ppm	ASTM D5185m	>20	1	0	0
Lead	ppm	ASTM D5185m	>20	1	0	<1
Copper	ppm	ASTM D5185m	>20	1	0	0
Tin	ppm	ASTM D5185m	>20	1	0	1
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		<1	0	0
Manganese	ppm	ASTM D5185m		<1	0	0
Magnesium	ppm	ASTM D5185m		2	0	1
Calcium	ppm	ASTM D5185m		0	0	<1
Phosphorus	ppm	ASTM D5185m		11	6	13
Zinc	ppm	ASTM D5185m		6	0	0
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	3	1	2
Sodium	ppm	ASTM D5185m		0	0	2
Potassium	ppm	ASTM D5185m	>20	<1	0	<1
Water	%	ASTM D6304	>0.05	0.002	0.002	0.004
ppm Water	ppm	ASTM D6304	>500	17	16	42
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.082	0.231	0.067
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	LIGHT
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	Submitted By: S	ervi <b>ce</b> Manager




# **OIL ANALYSIS REPORT**












# Ferrous Alloys

**GRAPHS** 











Certificate 12367

Laboratory Sample No.

: RP0036039 Lab Number : 06194090 Unique Number : 11056213

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 29 May 2024 **Tested** 

: 30 May 2024 Diagnosed : 31 May 2024 - Angela Borella

**ENERGY TRANSFER - COTTON VALLEY** 22394 HWY 371 COTTON VALLEY, LA US 71018

Contact: Service Manager Zach.Tinkle@energytransfer.com

Test Package : IND 2 To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: