



# FUEL REPORT

Sample Rating Trend



**NORMAL**



Machine Id  
**DIAMOND DA40NG N809L (S/N 40.NC268)**  
 Component  
**Right Jet Fuel**  
 Fluid  
**JET FUEL Type A (--- GAL)**

## DIAGNOSIS

### Recommendation

This is a baseline read-out on the submitted sample.

### Contamination

There is no bacteria or fungus (yeast and/or mold) present in the sample.

## SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		<b>WC06194567</b>	---	---
Sample Date	Client Info		<b>24 May 2024</b>	---	---
Machine Age	hrs	Client Info	<b>467</b>	---	---
Oil Age	hrs	Client Info	<b>0</b>	---	---
Oil Changed	Client Info		<b>N/A</b>	---	---
Sample Status			<b>NORMAL</b>	---	---



## CONTAMINATION

	method	limit/base	current	history1	history2
Water	WC Method		<b>NEG</b>	---	---

## MICROBIAL

	method	limit/base	current	history1	history2
Bacteria	CFU/ml WC-Method	$\geq 100000$	<b>0</b>	---	---
Yeast	CFU/ml WC-Method	$\geq 100000$	<b>0</b>	---	---
Mold	Colonies WC-Method	MODER	---	---	---

## SAMPLE IMAGES

	method	limit/base	current	history1	history2
Color				no image	no image
Bottom				no image	no image



# FUEL REPORT

## GRAPHS



Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513  
**Sample No.** : WC06194567      **Received** : 29 May 2024  
**Lab Number** : 06194567      **Tested** : 05 Jun 2024  
**Unique Number** : 11056690      **Diagnosed** : 05 Jun 2024 - Doug Bogart  
**Test Package** : TEST ( Additional Tests: Bacteria )

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**LIFT ACADEMY**  
 2753 CARGO DR  
 INDIANAPOLIS, IN  
 US 46241  
 Contact: JOEY LEACH  
 joey.leach@flywithlift.com  
 T: (812)799-6597  
 F: