OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Machine Id
1184
Component
Diesel Engine
Fluid
CHEVRON DELO 400 XLE 10W30 (--- GAL)

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
There is no indication of any contamination in the oil.

Fluid Condition
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0851778**	WC0733146	WC0733145
Sample Date		Client Info		**17 May 2024**	08 Dec 2023	14 Nov 2023
Machine Age	mls	Client Info		**104792**	100120	57148
Oil Age	mls	Client Info		**40000**	40000	40000
Oil Changed		Client Info		**Changed**	N/A	Changed
Sample Status				**NORMAL**	NORMAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Fuel		WC Method	>5	**<1.0**	<1.0	<1.0
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	**40**	12	36
Chromium	ppm	ASTM D5185m	>20	**3**	1	3
Nickel	ppm	ASTM D5185m	>4	**<1**	0	<1
Titanium	ppm	ASTM D5185m		**<1**	<1	<1
Silver	ppm	ASTM D5185m	>3	**<1**	0	0
Aluminum	ppm	ASTM D5185m	>20	**12**	6	21
Lead	ppm	ASTM D5185m	>40	**<1**	0	0
Copper	ppm	ASTM D5185m	>330	**66**	93	314
Tin	ppm	ASTM D5185m	>15	**1**	0	<1
Vanadium	ppm	ASTM D5185m		**<1**	0	0
Cadmium	ppm	ASTM D5185m		**<1**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**33**	78	42
Barium	ppm	ASTM D5185m		**2**	6	6
Molybdenum	ppm	ASTM D5185m		**2**	3	10
Manganese	ppm	ASTM D5185m		**1**	0	1
Magnesium	ppm	ASTM D5185m		**798**	698	706
Calcium	ppm	ASTM D5185m	2900	**1427**	1267	1370
Phosphorus	ppm	ASTM D5185m	1100	**826**	787	808
Zinc	ppm	ASTM D5185m	1200	**901**	813	856
Sulfur	ppm	ASTM D5185m	4000	**3023**	3091	2651

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	**7**	5	6
Sodium	ppm	ASTM D5185m		**4**	4	3
Potassium	ppm	ASTM D5185m	>20	**34**	16	56

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	**0.6**	0.2	0.4
Nitration	Abs/cm	*ASTM D7624	>20	**10.0**	7.8	10.1
Sulfation	Abs/.1mm	*ASTM D7415	>30	**22.6**	18.6	21.4

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**18.5**	13.4	17.9
Base Number (BN)	mg KOH/g	ASTM D2896	10.3	**7.32**	9.70	8.42

OIL ANALYSIS REPORT

FT-IR (Direct Trend)



Base Number



Viscosity @ 100°C



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**LIGHT**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	11.9	**12.0**	11.8	11.7

GRAPHS

Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Base Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC0851778
Lab Number : 06196873
Unique Number : 11058996
Test Package : MOB 2

Received : 31 May 2024
Tested : 03 Jun 2024
Diagnosed : 03 Jun 2024 - Sean Felton

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

LYNDEN TRANSPORT - SPRUCE GROVE
27340 ACHESON RD, ACHESON INDUSTRIAL PARK
ACHESON, AB
CA T7X 6B1
Contact: Mathieu Carby
mcarby@lynden.com
T:
F: