


OIL ANALYSIS REPORT



Machine Id **CATERPILLAR 306 8307 (S/N C6G605766)**

Right Final Drive

{not provided} (--- GA





Recommendation

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the

Fluid Condition


The condition of the oil is acceptable for the time in service.

ory2
ory2
ory2
ory2
ory2
ory2


Contact/Location: MIKE WYATT - TRANEW





OIL ANALYSIS REPORT













Certificate 12367

Laboratory Sample No.

Lab Number : 06197119 Unique Number : 11059242

: WC0913355 Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 31 May 2024

Tested : 03 Jun 2024 Diagnosed

: 03 Jun 2024 - Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.

US 28563 Contact: MIKE WYATT mwyatt@traderconstruction.com

TRADER CONSTRUCTION CO.

PO DRAWER 1578

NEW BERN, NC

T: (252)633-1399 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (252)638-4871

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.