



OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



Machine Id
ELEVATOR 2

Component
Gearbox

Fluid
AW HYDRAULIC OIL ISO 32 (--- QTS)



DIAGNOSIS

Recommendation

Sample unsuitable for testing. Also would be unable to tell biodegradable oil from regular hydraulic fluid.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number	Client Info			WC0774856	---	---
Sample Date	Client Info			21 May 2024	---	---
Machine Age	hrs	Client Info		0	---	---
Oil Age	hrs	Client Info		0	---	---
Oil Changed		Client Info		N/A	---	---
Sample Status				NORMAL	---	---







CONTAMINATION		method	limit/base	current	history1	history2
Water	WC Method		>0.2	NEG	---	---

SAMPLE IMAGES		method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image



OIL ANALYSIS REPORT

GRAPHS



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC0774856 **Received** : 31 May 2024
Lab Number : 06197230 **Tested** : 13 Jun 2024
Unique Number : 11059353 **Diagnosed** : 13 Jun 2024 - Doug Bogart
Test Package : MOB 2

MICHAEL G SENA LLC
 2 WHITNEY AVE
 EAST NORWICH, NY
 US 11732
 Contact: MICHAEL SENA
 mgsene@msvtp.com

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:
F: