


OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

E-ONE TRUCK 50

Component Hydraulic System

AW HYDRAULIC OIL ISO 46 (--- PNT)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

Elemental level of silicon (Si) above normal.


Fluid Condition


The condition of the oil is acceptable for the time in service.

			TOTAL	POLOLI POLOLI MOLOLI		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0930880	WC0801396	WC0683981
Sample Date		Client Info		18 May 2024	10 May 2023	20 Apr 2022
Machine Age	mls	Client Info		0	0	0
Oil Age	mls	Client Info		0	0	0
Oil Changed		Client Info		N/A	Not Changd	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	<1	<1	<1
Chromium	ppm	ASTM D5185m	>10	<1	0	<1
Nickel	ppm	ASTM D5185m	>10	0	<1	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>10	4	0	<1
Lead	ppm	ASTM D5185m	>10	<1	<1	<1
Copper	ppm	ASTM D5185m	>75	41	35	33
Tin	ppm	ASTM D5185m	>10	<1	0	<1
Antimony	ppm	ASTM D5185m				
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	2	0	2
Barium	ppm	ASTM D5185m	5	2	0	0
Molybdenum	ppm	ASTM D5185m	5	0	<1	<1
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m	25	9	8	8
Calcium	ppm	ASTM D5185m	200	91	83	80
Phosphorus	ppm	ASTM D5185m	300	364	345	356
Zinc	ppm	ASTM D5185m	370	459	454	452
Sulfur	ppm	ASTM D5185m	2500	1450	1535	1135
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	▲ 35	△ 32	▲ 37
Sodium	ppm	ASTM D5185m		0	0	<1
Potassium	ppm	ASTM D5185m	>20	2	<1	1
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	LIGHT
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
		43.77	NODAN		NODAN	NODM
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Odor Emulsified Water	scalar	*Visual *Visual	>0.1	NORML NEG	NORML	NEG




OIL ANALYSIS REPORT







FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	46	56.5	57.2	57.1
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image
CDADUC						

GRAPHS











Laboratory Sample No.

: WC0930880 Lab Number : 06200964 Unique Number : 11063087 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 05 Jun 2024

Tested : 06 Jun 2024

: 08 Jun 2024 - Don Baldridge Diagnosed

3003 E SOUTH BLVD MONTGOMERY, AL US 36104 Contact: ALLEN WIGGINS

MONTGOMERY FIRE DEPT

AWIGGINS@MONTGOMERYAL.GOV T: (334)625-2151

Certificate 12367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)