

OIL ANALYSIS REPORT

Area [BWR7442846] SUMITOMO 942016 (S/N VA0517781) Gearbox

Fluid **BELRAY SENTRA 220 (3 GAL)**

Recommendation

Resample at the next service interval to monitor.

Wear


All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.

Fluid Condition


The condition of the oil is acceptable for the time in service.




SAMPLE INFORM	1ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		BRI008189	BRI008223	BRI008224
Sample Date		Client Info		22 Apr 2024	22 Jan 2024	22 Jan 2024
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	ABNORMAL	NORMAL
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	111	4 317	25
Chromium	ppm	ASTM D5185m	>15	<1	4	0
Nickel	ppm	ASTM D5185m	>15	<1	0	0
Titanium	ppm	ASTM D5185m		0	0	<1
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	<1	0	<1
Lead	ppm	ASTM D5185m	>100	0	0	0
Copper	ppm	ASTM D5185m	>200	0	0	<1
Tin	ppm	ASTM D5185m	>25	<1	0	<1
Vanadium	ppm	ASTM D5185m		0	0	<1
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	4
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	1	0
Magnesium	ppm	ASTM D5185m		3	0	0
Calcium	ppm	ASTM D5185m		0	1	0
Phosphorus	ppm	ASTM D5185m		285	303	806
Zinc	ppm	ASTM D5185m		0	1	0
Sulfur	ppm	ASTM D5185m		594	308	1388
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	8	11	25
Sodium	ppm	ASTM D5185m		1	0	0
Potassium	ppm	ASTM D5185m	>20	2	<1	2
VISUAL		method	limit/base	current	history1	history2
	scalar	*Visual	limit/base NONE	current	history1 NONE	NONE
White Metal	scalar scalar	*Visual *Visual		NONE NONE		
White Metal Yellow Metal Precipitate		*Visual *Visual *Visual	NONE	NONE	NONE	NONE NONE NONE
White Metal Yellow Metal Precipitate Silt	scalar	*Visual *Visual	NONE NONE	NONE NONE NONE NONE	NONE	NONE
White Metal Yellow Metal Precipitate Silt	scalar scalar	*Visual *Visual *Visual	NONE NONE NONE	NONE NONE NONE NONE NONE	NONE NONE NONE	NONE NONE NONE
White Metal Yellow Metal Precipitate Silt Debris	scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *Visual	NONE NONE NONE	NONE NONE NONE NONE	NONE NONE NONE MODER	NONE NONE NONE NONE
VISUAL White Metal Yellow Metal Precipitate Silt Debris Sand/Dirt Appearance	scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual	NONE NONE NONE NONE	NONE NONE NONE NONE NONE	NONE NONE MODER NONE	NONE NONE NONE NONE NONE NORML
White Metal Yellow Metal Precipitate Silt Debris Sand/Dirt	scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *Visual	NONE NONE NONE NONE NONE	NONE NONE NONE NONE NONE	NONE NONE MODER NONE NONE	NONE NONE NONE NONE NONE
White Metal Yellow Metal Precipitate Silt Debris Sand/Dirt Appearance	scalar scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *Visual *Visual	NONE NONE NONE NONE NONE NORML	NONE NONE NONE NONE NONE NONE	NONE NONE MODER NONE NONE NORML	NONE NONE NONE NONE NONE NORML



OIL ANALYSIS REPORT







Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No. : BRI008189 : 06 Jun 2024 Received Lab Number : 06201926 Tested : 13 Jun 2024 Unique Number : 11069387 Diagnosed : 13 Jun 2024 - Wes Davis Test Package : IND 1 Certificate 12367 To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

100 QUALITY ST BRIDGEWATER, VA US 22812

PERDUE FARMS INC

US 22812 Contact: Ashley Jarvis ashley.jarvis@perdue.com T: (540)528-7828 12) F:

Contact/Location: Ashley Jarvis - PERBRIVA