

OIL ANALYSIS REPORT

__

Sample Rating Trend NO

NORMAL





Machine Id **VOLVO A30G 752469**

Component
Transmission (Auto)
Fluid
DEXRON III (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the fluid.


Fluid Condition

The condition of the fluid is acceptable for the time in service.

				Jun 2024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
	IATION		IIIIIII Dase			
Sample Number		Client Info		ML0002006		
Sample Date		Client Info		04 Jun 2024		
Machine Age	hrs	Client Info		1889		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>160	15		
Chromium	ppm	ASTM D5185m	>5	0		
Nickel	ppm	ASTM D5185m	>5	2		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m	>5	0		
Aluminum	ppm	ASTM D5185m	>50	16		
Lead	ppm	ASTM D5185m	>50	0		
Copper	ppm	ASTM D5185m	>225	15		
Tin	ppm	ASTM D5185m	>10	3		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		103		
Barium	ppm	ASTM D5185m		1		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		2		
Magnesium	ppm	ASTM D5185m		1		
Calcium	ppm	ASTM D5185m		92		
Phosphorus	ppm	ASTM D5185m		208		
Zinc	ppm	ASTM D5185m		14		
Sulfur	ppm	ASTM D5185m		1834		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	10		
Sodium	ppm	ASTM D5185m		6		
Potassium	ppm	ASTM D5185m	>20	5		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.1	NEG		
Free Water	scalar	*Visual		NEG		





OIL ANALYSIS REPORT



FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	35.0	28.2		
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image
CDADHS						

Ferrous Alloys mdd







Laboratory

Sample No. : ML0002006 Lab Number : 06205201 Unique Number : 11072662

Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 10 Jun 2024

Tested : 12 Jun 2024 Diagnosed

: 12 Jun 2024 - Doug Bogart

160 KENTMERE COURT WINCHESTER, VA US 22603

Contact: DAKOTA HARTLEY dhartley@mcclung-logan.com

MCCLUNG-LOGAN EQUIPMENT CO - WINCHESTER

Certificate 12367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: VOLVO4589 [WUSCAR] 06205201 (Generated: 06/12/2024 10:27:09) Rev: 1

Contact/Location: DAKOTA HARTLEY - VOLVO4589

F: (540)722-4441