

## **OIL ANALYSIS REPORT**

## Area DONNA PENNANT LS-043024-01C

Component Chain Fluid {not provided} (--- GAL)

## DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample.

						•
		J.		Jun2024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0946794		
Sample Date		Client Info		06 Jun 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.2	NEG		
Free Water	scalar	*Visual		NEG		
SAMPLE IMAGE	S	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image

Sample Rating Trend




NORMAL



## **OIL ANALYSIS REPORT**

GRAPHS



Report Id: BASTAR [WUSCAR] 06206035 (Generated: 07/10/2024 12:37:05) Rev: 1

Contact/Location: DONNA PENNANT - BASTAR Page 2 of 2