


OIL ANALYSIS REPORT

Sample Rating Trend









WOLVO A45G 342394

Component
Drop Box

VOLVO SUPER GEAR OIL 75W-80-GO102 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil


Fluid Condition

The condition of the oil is acceptable for the time in service.

P267351 Jun 2023
lun 2023 4
4
naod
na o cl
nged
RMAL
history2
IEG
history2
3
1
:1
:1
history2
19
:1
7
677
2
5056
history2
1
:1
history2
IONE
IORML
IORML
UNIVIL
IEG





OIL ANALYSIS REPORT



FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445		51.9	49.9	69.9
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image
GRAPHS						

Ferrous Alloys 100 1/20 Non-ferrous Metals







Laboratory

Sample No. : ML0002738 Lab Number : 06208144

Unique Number : 11075605

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 12 Jun 2024

Tested : 14 Jun 2024 Diagnosed : 14 Jun 2024 - Don Baldridge

MCCLUNG-LOGAN EQUIPMENT CO - RICHMOND

1345 MOUNTAIN ROAD GLEN ALLEN, VA US 23060

Contact: KYLE RATLIFFE KRATLIFFE@MCCLUNG-LOGAN.COM

Test Package : CONST Certificate 12367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (804)266-1611