

PROBLEM SUMMARY

Sample Rating Trend




SPAM MFC
Machine Id
B58890 - DODGE DAY MIXER 3

Gearbox

PETRO CANADA PURITY FG EP GEAR OIL 220 (30 QTS)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS								
Sample Status			SEVERE	ABNORMAL	ABNORMAL			
Particles >4µm	ASTM D7647	>20000	155867	<u></u> 141733	<u>\$\text{253508}\$</u>			
Particles >6µm	ASTM D7647	>5000	A 84417	93476	<u>128419</u>			
Particles >14μm	ASTM D7647	>640	1920	<u></u> 4 3582	<u>\$\text{2364}\$</u>			
Oil Cleanliness	ISO 4406 (c)	>21/19/16	2 4/24/18	<u>4</u> 24/24/19	<u>\$\text{\scale}\$ 25/24/18</u>			

Customer Id: PRODUB Sample No.: WC0943528 Lab Number: 06208693 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter			?	We recommend you service the filters on this component.		
Resample			?	Resample in 30-45 days to monitor this situation.		
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.		
Check Seals			?	Check seals and/or filters for points of contaminant entry.		

HISTORICAL DIAGNOSIS

05 Mar 2024 Diag: Don Baldridge

VISCOSITY



We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. Viscosity of sample indicates oil is within ISO 150 range, advise investigate. Confirm oil type. The AN level is acceptable for this fluid.



VISCOSITY



18 Dec 2023 Diag: Don Baldridge

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. Viscosity of sample indicates oil is within ISO 150 range, advise investigate. Confirm oil type. The AN level is acceptable for this fluid.





18 Sep 2023 Diag: Wes Davis

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.






OIL ANALYSIS REPORT

SPAM MFC

B58890 - DODGE DAY MIXER 3

Gearbox

PETRO CANADA PURITY FG EP GEAR OIL 220 (30 QTS)





DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code.


Fluid Condition


The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.


. 220 (30 QTS)		:t2016 Oct201	7 Aug2018 Jun2019 Apr20	120 Dec2020 Sep2021 Jan2023 S	ep2023 Jun20	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0943528	WC0894864	WC0872378
Sample Date		Client Info		12 Jun 2024	05 Mar 2024	18 Dec 2023
Machine Age	mths	Client Info		0	0	0
Oil Age	mths	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	ABNORMAL	ABNORMAL
CONTAMINATION	٧	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	33	75	52
Chromium	ppm	ASTM D5185m	>15	0	0	0
Nickel	ppm	ASTM D5185m	>15	0	0	0
Titanium	ppm	ASTM D5185m		0	0	<1
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	0	<1	0
Lead	ppm	ASTM D5185m	>100	0	0	0
Copper	ppm	ASTM D5185m	>200	0	0	0
Tin	ppm	ASTM D5185m	>25	0	<1	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	<1	<1
Magnesium	ppm	ASTM D5185m		0	0	0
Calcium	ppm	ASTM D5185m		0	2	1
Phosphorus	ppm	ASTM D5185m		456	479	436
Zinc	ppm	ASTM D5185m		<1	0	0
Sulfur	ppm	ASTM D5185m		1226	907	894
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	4	5	5
Sodium	ppm	ASTM D5185m		<1	<1	0
Potassium	ppm	ASTM D5185m	>20	0	0	0
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	<u> </u>	<u> </u>	<u>^</u> 253508
Particles >6μm		ASTM D7647	>5000	A 84417	△ 93476	<u>128419</u>
Particles >14µm		ASTM D7647	>640	<u> </u>	<u>▲</u> 3582	<u>^</u> 2364
Particles >21µm		ASTM D7647	>160	237	<u>▲</u> 342	<u>▲</u> 321
Particles >38μm		ASTM D7647	>40	4	6	1
Particles >71µm		ASTM D7647		0	3	0
Oil Cleanliness		ISO 4406 (c)	>21/19/16	2 4/24/18	<u>4</u> 24/24/19	<u>\$\text{\$\exitt{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\exitt{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\exitt{\$\text{\$\$\}}\$}}}\$}}}}}}}}}}}}}}}}}}}}}}}}}}}}</u>
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.51	0.57	0.52	0.48




OIL ANALYSIS REPORT









VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


FLUID PROPERTIES		method	limit/base	current	nistory1	history2
Visc @ 40°C	cSt	ASTM D445	205.8	217	158	157

Color

Bottom

SAMPLE IMAGES









Certificate 12367

Laboratory Sample No.

Lab Number : 06208693

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : WC0943528

Unique Number : 11076154

Received **Tested**

: 13 Jun 2024 : 14 Jun 2024 Diagnosed

: 14 Jun 2024 - Wes Davis

Test Package : IND 2 (Additional Tests: PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

PROGRESSIVE PROCESSING INC

1205 CHAVENELLE CT DUBUQUE, IA

US 52002 Contact: BLAINE PURDY bepurdy@hormel.com

T: (563)557-4500 F: (563)557-4508

Contact/Location: BLAINE PURDY - PRODUB