














# OIL ANALYSIS REPORT



VISUAL	method	limit/base	current	history1	history2	
White Metal	scalar	*Visual	NONE	NONE	---	---
Yellow Metal	scalar	*Visual	NONE	NONE	---	---
Precipitate	scalar	*Visual	NONE	NONE	---	---
Silt	scalar	*Visual	NONE	NONE	---	---
Debris	scalar	*Visual	NONE	NONE	---	---
Sand/Dirt	scalar	*Visual	NONE	NONE	---	---
Appearance	scalar	*Visual	NORML	NORML	---	---
Odor	scalar	*Visual	NORML	NORML	---	---
Emulsified Water	scalar	*Visual	>0.2	NEG	---	---
Free Water	scalar	*Visual		NEG	---	---

FLUID PROPERTIES	method	limit/base	current	history1	history2	
Visc @ 100°C	cSt	ASTM D445	14.5	▲ 12.1	---	---

### GRAPHS



**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513  
**Sample No.** : WC0907660      **Received** : 17 Jun 2024  
**Lab Number** : 06211318      **Tested** : 19 Jun 2024  
**Unique Number** : 11084182      **Diagnosed** : 19 Jun 2024 - Angela Borella  
**Test Package** : MAR 2 ( Additional Tests: FuelDilution, PercentFuel, TAN Man )

**SEAWARD SERVICES**  
 222 PEARL ST  
 NEW ALBANY, IN  
 US 47150  
 Contact: PETER CHARBONNET  
 PCHARBONNET@HMS-SEAWARD.COM

To discuss this sample report, contact Customer Service at 1-800-237-1369.  
 \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.  
 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)