


## **PROBLEM SUMMARY**

### Area COLD MILL/CM-3STD-1S SOUTH 3-STAND REWIND GEARBOX 1526-007-7540

Gearbox Eluid

PETRO CANADA ENDURATEX EP 460 (100 GAL)

### COMPONENT CONDITION SUMMARY



### RECOMMENDATION

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS							
Sample Status		SEVERE	SEVERE	SEVERE			
Particles >4µm	ASTM D7647 >20000	296856	<b>1</b> 71399	<b>1</b> 37609			
Particles >6µm	ASTM D7647 >5000	<b>134015</b>	<b>A</b> 73957	▲ 53153			
Particles >14µm	ASTM D7647 >640	<u> </u>	<b>1</b> 929	<b>1</b> 453			
Oil Cleanliness	ISO 4406 (c) >21/19/	/16 🔺 25/24/19	🔺 25/23/18	<b>4</b> /23/18			


Customer Id: CONMUSAL Sample No.: KFS0004852 Lab Number: 06211583 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com



RECOMMENDED ACTIONS							
Action Change Filter	Status	Date	Done By ?	<b>Description</b> We recommend you service the filters on this component.			
Resample			?	Resample in 30-45 days to monitor this situation.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Seals			?	Check seals and/or filters for points of contaminant entry.			

### HISTORICAL DIAGNOSIS



### 16 May 2024 Diag: Wes Davis

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





#### 16 Apr 2024 Diag: Wes Davis

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





### 29 Feb 2024 Diag: Wes Davis

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





## **OIL ANALYSIS REPORT**

#### Area COLD MILL/CM-3STD-1S Machine to SOUTH 3-STAND REWIND GEARBOX 1526-007-7540 Component

**Gearbox** 

PETRO CANADA ENDURATEX EP 460 (100 GAL)

### DIAGNOSIS

### Recommendation

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

### Wear


All component wear rates are normal.

### Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

### Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.




SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KFS0004852	KFS0004441	KFS0004478
Sample Date		Client Info		13 Jun 2024	16 May 2024	16 Apr 2024
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	SEVERE
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	25	16	9
Chromium	ppm	ASTM D5185m	>15	<1	0	0
Nickel	ppm	ASTM D5185m	>15	<1	0	<1
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	2	0	<1
Lead	ppm	ASTM D5185m	>100	<1	0	<1
Copper	ppm	ASTM D5185m	>200	<1	0	<1
Tin	ppm	ASTM D5185m	>25	<1	0	<1
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	55	32	34	36
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	0	<1	0	0
Manganese	ppm	ASTM D5185m	0	<1	0	<1
Magnesium	ppm	ASTM D5185m	2	<1	<1	1
Calcium	ppm	ASTM D5185m	6	0	<1	1
Phosphorus	ppm	ASTM D5185m	240	226	205	209
Zinc	ppm	ASTM D5185m	3	2	<1	0
Sulfur	ppm	ASTM D5185m	10310	8451	8372	8735
CONTAMINANTS	\$	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	9	8	8
Sodium	ppm	ASTM D5185m		1	0	2
Potassium	ppm	ASTM D5185m	>20	<1	0	3
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	<b>296856</b>	<b>1</b> 71399	137609
Particles >6µm		ASTM D7647	>5000	<b>1</b> 34015	▲ 73957	▲ 53153
Particles >14µm		ASTM D7647	>640	<b>A</b> 3112	<b>1</b> 929	<b>1</b> 453
Particles >21µm		ASTM D7647	>160	211	205	151
Particles >38µm		ASTM D7647	>40	1	2	1
Particles >71µm		ASTM D7647		1	0	0
Oil Cleanliness		ISO 4406 (c)	>21/19/16	<b>4</b> 25/24/19	▲ 25/23/18	4/23/18
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.5	0.49	0.48	0.53
3:12:12) Rev: 1				Submitted	By: COLD MILL	- Josh Edwards


Report Id: CONMUSAL [WUSCAR] 06211583 (Generated: 06/18/2024 18:12:12) Rev: 1


Submitted By: COLD MILL - Josh Edwards Page 3 of 4




# **OIL ANALYSIS REPORT**










MOLIAI		and a first of	12	t	Internet and	la la tarra O
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	452	423	427	434
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color						
Bottom						



Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 CONSTELLIUM Sample No. 4805 SECOND STREET : KFS0004852 Received : 17 Jun 2024 Lab Number : 06211583 Tested : 18 Jun 2024 MUSCLE SHOALS, AL Unique Number : 11084447 Diagnosed : 18 Jun 2024 - Wes Davis US 35661 Test Package : IND 2 (Additional Tests: PrtCount) **Contact: Randy Nichols** Certificate 12367 randall.nichols@constellium.com To discuss this sample report, contact Customer Service at 1-800-237-1369. T: (256)386-6956 \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F:

Report Id: CONMUSAL [WUSCAR] 06211583 (Generated: 06/18/2024 18:12:13) Rev: 1

Submitted By: COLD MILL - Josh Edwards

Page 4 of 4