

FUEL REPORT

Sample Rating Trend



Machine Id

PASCO WEST COMPOUNT TANK 1

Diesel Fuel

No.2 DIESEL FUEL (ULTRALOW SULPHUR

Recommendation

All laboratory tests indicate that this sample meets specifications for No.2 ultra-low-sulfur diesel fuel.

Corrosion

All metal levels are normal indicating no corrosion in the system.

Contaminants

There is no bacteria or fungus (yeast and/or mold) indicated in the sample. The water content is negligible. There is no indication of any contamination in the fuel.


Fuel Condition


Sulfur value derived by ASTM D5453 method for ULSD validation. Sulfur level is acceptable for ULSD specification.

R) (GAL)		Aug	2018	Mar2024 Jun20	124	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number Sample Date Machine Age Sample Status	mls	Client Info Client Info Client Info		WCDF4631 13 Jun 2024 0 NORMAL	WCDF4565 20 Mar 2024 0 ABNORMAL	WCDF00727 16 Aug 2018 0 NORMAL
PHYSICAL PROP	ERTIES	method	limit/base	current	history1	history2
ASTM Color Visc @ 40°C	scalar cSt	*ASTM D1500 ASTM D445	3.0	L0.5 2.28	L2.5 2.26	L0.5 2.69
SULFUR CONTE	NT	method	limit/base	current	history1	history2
Sulfur Sulfur (UVF)	ppm ppm	ASTM D5185m ASTM D5453	10	26 5	12 7	6 8
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon Sodium Potassium Water ppm Water % Gasoline % Biodiesel HEAVY METALS Aluminum Nickel Lead Vanadium Iron Calcium Magnesium Phosphorus	ppm ppm ppm % ppm % % ppm ppm ppm ppm pp	ASTM D5185m ASTM D5185m ASTM D6304 ASTM D6304 *In-House *In-House method ASTM D5185m	<0.1 <0.1 <0.1 <0.1 <0.1	0 2 <1 0.004 43 0.0 0.0 current 0 0 <1 0 0 0 0 0	0 2 <1 0.004 45 0.0 0.0 history1 0 0 0 <1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0.004 40 0.0 0.0 0 0 0 0 0 <1
Zinc	ppm	ASTM D5185m		0	0	0
SAMPLE IMAGES		method	limit/base	current	history1	history2
Bottom						no image



FUEL REPORT







Certificate 12367

Laboratory

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No. : WCDF4631 Lab Number : 06215232

Unique Number : 11088096

Received Tested Diagnosed

: 19 Jun 2024 : 21 Jun 2024

: 21 Jun 2024 - Doug Bogart

TANK WIZARDS 1511 MASTERS RD NW PALM BAY, FL US 32907

Test Package: DF-5 (Additional Tests: PrtCount, Screen) To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Contact: WENDALL STRODERD wendall@tankwizards.com T: (321)427-5149

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) Report Id: TANPAL [WUSCAR] 06215232 (Generated: 06/21/2024 17:07:45) Rev: 1

Contact/Location: 321-285-8878 X1 - WENDALL STRODERD - TANPAL

F: (321)574-4131