

### **OIL ANALYSIS REPORT**

Iron

Tin

Machine Ic

# KAESER BSD 50T 6037742 (S/N 1376)

Compressor

KAESER SIGMA (OEM) M-460 (--- QTS)

#### DIAGNOSIS

#### Recommendation

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

#### Wear


All component wear rates are normal.

#### Contamination

There is a high amount of particulates present in the oil.

#### Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.



Acid Number (AN)

mg KOH/g ASTM D8045 1.0


0.39


0.41


0.37




## **OIL ANALYSIS REPORT**











VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	LIGHT	NONE	LIGHT
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	45	53.0	51.4	49.4
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color						

Bottom

10

10

60

55 (0-0<del>1</del>) tso

40


35

Laboratory

Sample No.

Lab Number : 06216928

Unique Number : 11089792



: 24 Jun 2024

: 24 Jun 2024 - Don Baldridge



2601 W BETHEL RD GRAPEVINE, TX US 76051 Contact: Service Manager

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Tested

Diagnosed

Report Id: AMAGRA [WUSCAR] 06216928 (Generated: 06/24/2024 17:47:40) Rev: 2

Certificate 12367

Contact/Location: Service Manager - AMAGRA Page 2 of 2

T: F:

Test Package : IND 2 (Additional Tests: KF, PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.