


OIL ANALYSIS REPORT



OKLAHOMA/102/EG - OTHER SERVICE 68.14L [OKLAHOMA^102^EG - OTHER SERVICE]

Hydraulic System

MOBIL MOBILTRANS AST 30 (59 GAL)







DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. (Customer Sample Comment: 2120 hours)

Wear

All component wear rates are normal.

Contamination

The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil.

Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


| AST 30 (59 GAL) Sumbol 1 Sumbol 1 New Job 2 New Job 2 Sumbol 3 Sumbol 4 | | | | | | |
|--|--------|--------------|------------|-------------|-------------|-------------|
| SAMPLE INFOR | MATION | method | limit/base | current | history1 | history2 |
| Sample Number | | Client Info | | WC0925155 | WC0864301 | WC0746906 |
| Sample Date | | Client Info | | 20 Jun 2024 | 08 Dec 2023 | 08 Jul 2023 |
| Machine Age | hrs | Client Info | | 2120 | 1877 | 1618 |
| Oil Age | hrs | Client Info | | 2120 | 1877 | 1371 |
| Oil Changed | | Client Info | | N/A | N/A | N/A |
| Sample Status | | | | NORMAL | ATTENTION | NORMAL |
| CONTAMINATIO | N | method | limit/base | current | history1 | history2 |
| Water | | WC Method | >0.1 | NEG | NEG | NEG |
| WEAR METALS | | method | limit/base | current | history1 | history2 |
| ron | ppm | ASTM D5185m | >20 | 7 | 6 | 6 |
| Chromium | ppm | ASTM D5185m | >10 | <1 | <1 | 0 |
| Nickel | ppm | ASTM D5185m | >10 | <1 | <1 | 0 |
| Titanium | ppm | ASTM D5185m | | <1 | <1 | <1 |
| Silver | ppm | ASTM D5185m | | <1 | 0 | 0 |
| Aluminum | ppm | ASTM D5185m | >10 | 3 | 2 | 3 |
| _ead | ppm | ASTM D5185m | >10 | 2 | 1 | <1 |
| Copper | ppm | ASTM D5185m | >75 | 10 | 11 | 9 |
| Γin | ppm | ASTM D5185m | >10 | <1 | <1 | <1 |
| Vanadium | ppm | ASTM D5185m | | <1 | 0 | <1 |
| Cadmium | ppm | ASTM D5185m | | <1 | <1 | 0 |
| ADDITIVES | | method | limit/base | current | history1 | history2 |
| Boron | ppm | ASTM D5185m | | 5 | 4 | 4 |
| Barium | ppm | ASTM D5185m | | 2 | 0 | 0 |
| Molybdenum | ppm | ASTM D5185m | | <1 | <1 | <1 |
| Manganese | ppm | ASTM D5185m | | <1 | <1 | <1 |
| Magnesium | ppm | ASTM D5185m | | 11 | 11 | 12 |
| Calcium | ppm | ASTM D5185m | | 1736 | 1792 | 1898 |
| Phosphorus | ppm | ASTM D5185m | | 895 | 876 | 842 |
| Zinc | ppm | ASTM D5185m | | 1086 | 1089 | 1107 |
| Sulfur | ppm | ASTM D5185m | | 4519 | 4830 | 5276 |
| CONTAMINANTS | S | method | limit/base | current | history1 | history2 |
| Silicon | ppm | ASTM D5185m | >20 | 4 | 4 | 4 |
| Sodium | ppm | ASTM D5185m | | 0 | 0 | 2 |
| Potassium | ppm | ASTM D5185m | >20 | 4 | 3 | 1 |
| FLUID CLEANLII | NESS | method | limit/base | current | history1 | history2 |
| Particles >4µm | | ASTM D7647 | | 1524 | 25203 | 2547 |
| Particles >6µm | | ASTM D7647 | >2500 | 101 | 4902 | 322 |
| Particles >14μm | | ASTM D7647 | >640 | 7 | 84 | 18 |
| Particles >21μm | | ASTM D7647 | >160 | 2 | 16 | 3 |
| Particles >38μm | | ASTM D7647 | >40 | 0 | 0 | 0 |
| Particles >71μm | | ASTM D7647 | >10 | 0 | 0 | 0 |
| Oil Cleanliness | | ISO 4406 (c) | >/18/16 | 18/14/10 | 22/19/14 | 19/16/11 |
| FLUID DEGRAD | ATION | method | limit/base | current | history1 | history2 |
| | | | | | | |


1.09




OIL ANALYSIS REPORT









| VISUAL | | method | | | | history2 |
|-------------------------|--------|---------|------------|---------|----------|----------|
| White Metal | scalar | *Visual | NONE | NONE | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | NONE | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | NONE | NONE | NONE |
| Silt | scalar | *Visual | NONE | NONE | NONE | NONE |
| Debris | scalar | *Visual | NONE | NONE | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | NONE | NONE | NONE |
| Appearance | scalar | *Visual | NORML | NORML | NORML | NORML |
| Odor | scalar | *Visual | NORML | NORML | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.1 | NEG | NEG | NEG |
| Free Water | scalar | *Visual | | NEG | NEG | NEG |
| FLUID PROPER | ΓIES | method | limit/base | current | history1 | history2 |

| FLUID PROPER | RIIES | metnoa | ilmit/base | current | nistory i | nistory2 |
|--------------|-------|-----------|------------|---------|-----------|----------|
| Visc @ 40°C | cSt | ASTM D445 | 57.6 | 43.2 | 43.4 | 43.8 |

| 04440 | | | 050 |
|-------|-----|-----|-----|
| SAMP | LE. | IMA | GES |
| | | | |

Color

Bottom

491 520 122,880

> 30,720 7,680

> > 1,920




Particle Count







1999 Clea













Certificate 12367

Laboratory Sample No.

: WC0925155 Lab Number : 06218744 Unique Number : 11096941 Test Package : CONST

cSt (40°C)

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 24 Jun 2024

Tested : 25 Jun 2024 Diagnosed : 26 Jun 2024 - Don Baldridge

SHERWOOD CONSTRUCTION CO INC 3219 WEST MAY ST

WICHITA, KS US 67213 Contact: DOUG KING

doug.king@sherwood.net T: (316)617-3161

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: x: