

### **OIL ANALYSIS REPORT**

Tin

Sample Rating Trend

WEAR

Machine Id

# JOHN DEERE 333G 1T0333GMHRF459867

**Diesel Engine** 

JOHN DEERE ENGINE OIL PLUS 50 II 15W40 (--- GAL)

#### DIAGNOSIS

#### Recommendation

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

#### A Wear


The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). All other metal levels are typical for a new component breaking in.

#### Contamination

There is no indication of any contamination in the oil.


#### Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.





## **OIL ANALYSIS REPORT**



Contact/Location: DAVID ZIEG - JAMASH