

## **OIL ANALYSIS REPORT**

## Area **40 MILE [46004111]** Machine Id **TGY001230 - SHELL OMALA S5 WIND 320 (S/N BM0054)**


New (Unused) Oil

{not provided} (--- LTR)

## DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample.




Acid Number (AN) mg KOH/g ASTM D8045 Report Id: NORDEX [WUSCAR] 06234375 (Generated: 07/16/2024 16:03:01) Rev: 1

45

0.90 --- ---Contact/Location: DEVIN LINEHAN - NORDEX Page 1 of 2







Sample Rating Trend



## **OIL ANALYSIS REPORT**





To discuss this sample report, contact Customer Service at 1-800-237-1369. DLinehan@nordex-online.com \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (312)386-4124 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (312)386-7102

Report Id: NORDEX [WUSCAR] 06234375 (Generated: 07/16/2024 16:03:01) Rev: 1

Contact/Location: DEVIN LINEHAN - NORDEX