

# **FUEL REPORT**

Sample Rating Trend

# NORMAL

#### Machine Id

### Koehler 275 park manor rehab 358032 special-132663-81 Component Diesel Fuel Fluid

No.2 DIESEL FUEL (ULTRALOW SULPHUR) (--- GAL)

#### Recommendation

No corrective action is recommended at this time.

#### Corrosion

All metal levels are normal indicating no corrosion in the system.

#### Contaminants


There is no indication of any contamination in the fuel.

#### **Fuel Condition**

The condition of the fuel is acceptable for the time in service.

SAMPLE INFORM	1ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0921735		
Sample Date		Client Info		10 Jul 2024		
Machine Age	hrs	Client Info		0		
Sample Status				NORMAL		
SULFUR CONTER	ΝT	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185m	10	0		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	<1.0	2		
Sodium	ppm	ASTM D5185m	<0.1	2		
Potassium	ppm	ASTM D5185m	<0.1	0		
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185m	<0.1	0		
Nickel	ppm	ASTM D5185m	<0.1	0		
Lead	ppm	ASTM D5185m	<0.1	0		
Vanadium	ppm	ASTM D5185m	<0.1	0		
Iron	ppm	ASTM D5185m	<0.1	0		
Calcium	ppm	ASTM D5185m	<0.1	0		
Magnesium	ppm	ASTM D5185m	<0.1	2		
Phosphorus	ppm	ASTM D5185m	<0.1	0		
Zinc	ppm	ASTM D5185m	<0.1	0		
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color					no image	no image

Color	4	no image	no image
Bottom		no image	no image








## **FUEL REPORT**

GRAPHS



Submitted By: Chris Halvorsen Page 2 of 2