

OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

SHUTTLE WAGON NXT423 ARIES2303

Front Left Final Drive

UTH (--- GAL)

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The condition of the oil is acceptable for the time in service.

				Jul2024		
	AATION		11 11 11			
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		ML0002694		
Sample Date		Client Info		10 Jul 2024		
Machine Age	hrs	Client Info		1034		
Oil Age	hrs	Client Info		1034		
Oil Changed		Client Info		Changed		
Sample Status				NORMAL		
CONTAMINATION	N	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>500	354		
Chromium	ppm	ASTM D5185m	>10	4		
Nickel	ppm	ASTM D5185m	>10	0		
Fitanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	<1		
₋ead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m	>50	17		
Γin	ppm	ASTM D5185m	>10	0		
/anadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		117		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		5		
Magnesium	ppm	ASTM D5185m		0		
Calcium	ppm	ASTM D5185m		619		
Phosphorus	ppm	ASTM D5185m		747		
Zinc	ppm	ASTM D5185m		1127		
Sulfur	ppm	ASTM D5185m		11865		
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	30		
Sodium	ppm	ASTM D5185m		3		
Potassium	ppm	ASTM D5185m	>20	3		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	MODER		
ellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	MODER		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.2	NEG		
ree Water	scalar	*Visual		NEG		
:57:24) Dov: 1				0	tod By: Sonvice	Alox Andorco





OIL ANALYSIS REPORT



Visc @ 40°C	FLUID PROPERTIES		method	limit/base	current	history1	history2
Color no image no image no image	Visc @ 40°C	cSt	ASTM D445		101		
	SAMPLE IMAGES		method	limit/base	current	history1	history2
Bottom no image no image no image	Color				no image	no image	no image
	Bottom				no image	no image	no image

Ferrous Alloys 400 350 150 100









Certificate 12367

Laboratory Sample No. : ML0002694 Lab Number : 06236550 Unique Number : 11125384

Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 15 Jul 2024 Tested

: 16 Jul 2024 Diagnosed : 17 Jul 2024 - Sean Felton

MCCLUNG-LOGAN EQUIPMENT CO - RICHMOND

1345 MOUNTAIN ROAD GLEN ALLEN, VA US 23060

Contact: Alex Anderson aanderson@mcclung-logan.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

F: (804)266-1611 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)