

OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id DEBRIS SAMPLE

Component Unknown Component Fluid {not provided} (--- GAL)

DIAGNOSIS

Recommendation


Debris appears to be a rubber-like substance.

				Jul2024		
SAMPLE INFORM	1ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC06239547		
Sample Date		Client Info		16 Jul 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method		NEG		
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image
PrtFilter				RE	no image	no image



OIL ANALYSIS REPORT

GRAPHS



Contact/Location: DAVE KOEHNE - STEBOL

Page 2 of 2