

OIL ANALYSIS REPORT

Area **Powerblock** Machine Id **Induced Draft Fan**

Prive End Bearing Fluid ROYAL PURPLE SYNFILM GT 68 (--- GAL)

DIAGNOSIS

A Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor.

Wear


All component wear rates are normal.

Contamination

There is a moderate amount of visible silt present in the sample.

Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.





Sample Rating Trend




OIL ANALYSIS REPORT







VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	LIGHT	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	A MODER	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>2	0.2%	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
FLUID PROPERT Visc @ 40°C	IES cSt	method ASTM D445	limit/base	current 65.7	history1 64.8	history2 71.8
	cSt				,	
Visc @ 40°C	cSt	ASTM D445	68	65.7	64.8	71.8



To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: VEOCAR [WUSCAR] 06239610 (Generated: 07/21/2024 12:08:00) Rev: 1

Submitted By: JOHNNY STONE Page 2 of 2

T:

F: