




# OIL ANALYSIS REPORT

Area  
**TBN**  
 Machine Id  
**TBN-QC10**  
 Component  
**Oil**  
 Fluid  
 {not provided} (--- GAL)

Sample Rating Trend



**NORMAL**



## DIAGNOSIS



| SAMPLE INFORMATION |             | method      | limit/base | current            | history1    | history2    |
|--------------------|-------------|-------------|------------|--------------------|-------------|-------------|
| Sample Date        | Client Info |             |            | <b>02 Mar 2023</b> | 01 Mar 2023 | 01 Mar 2023 |
| Machine Age        | HR          | Client Info |            | <b>0</b>           | 0           | 0           |
| Oil Age            | HR          | Client Info |            | <b>0</b>           | 0           | 0           |
| Oil Changed        |             | Client Info |            | <b>N/A</b>         | N/A         | N/A         |
| Sample Status      |             |             |            | <b>NORMAL</b>      | NORMAL      | NORMAL      |

| SAMPLE IMAGES |  | method | limit/base | current | history1        | history2        |
|---------------|--|--------|------------|---------|-----------------|-----------------|
| Color         |  |        |            |         | <i>no image</i> | <i>no image</i> |
| Bottom        |  |        |            |         | <i>no image</i> | <i>no image</i> |



# OIL ANALYSIS REPORT

## GRAPHS



Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513  
**Sample No.** :  
**Lab Number** : Q0004GDN  
**Unique Number** : 15893355  
**Test Package** : TEST

**WEARCHECK LUBRICATION SERVICES QA ACCOUNT**  
 501 Madison Ave  
 Cary, NC  
 US 27513  
 Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (919)379-4102  
 F: (919)379-4050