


OIL ANALYSIS REPORT

Sample Rating Trend





ICP Machine Id ARCOS-1-AM/900

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history 1	history 2
Sample Date		Client Info		30 Jun 2023	30 Jun 2023	30 Jun 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						


SAMPLE IMAGES	method	limit/base	current	history 1	history 2
Color			no image	no image	no image
Bottom			no image	no image	no image



OIL ANALYSIS REPORT

GRAPHS







Certificate L2367

Laboratory Sample No. Lab Number Test Package : TEST

Unique Number : 15987244

: Q0004H8S

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 30 Jun 2023

Diagnosed : 30 Jun 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050