


## **OIL ANALYSIS REPORT**

Sample Rating Trend



ICP
Machine Id
ARCOS-1-AM/900

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


Sample Date         Client Info         03 Jul 2023           Machine Age         HR         Client Info         0         0         0           Oil Age         HR         Client Info         0         0         0           Oil Changed         Client Info         N/A         N/A         N/A	SAMPLE INFORMATION		method	limit/base	current	history 1	history 2
Oil Age HR Client Info <b>0</b> 0 0	Sample Date		Client Info		03 Jul 2023	03 Jul 2023	03 Jul 2023
g-	Machine Age	HR	Client Info		0	0	0
Oil Changed Client Info N/A N/A N/A	Oil Age	HR	Client Info		0	0	0
	Oil Changed		Client Info		N/A	N/A	N/A
Sample Status	Sample Status						


SAMPLE IMAGES	method	limit/base	current	history 1	history 2	
Color			no image	no image	no image	
Bottom			no image	no image	no image	



## **OIL ANALYSIS REPORT**

## **GRAPHS**







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 16000486 Test Package : TEST

: Q0004H9O

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 03 Jul 2023

Diagnosed : 03 Jul 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave

Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050