


OIL ANALYSIS REPORT

Sample Rating Trend



ICP Machine Id ARCOS-1-S-21/50

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


| SAMPLE INFORM | IATION | method | limit/base | current | history 1 | history 2 |
|---------------|--------|-------------|------------|-------------|-------------|-------------|
| Sample Date | | Client Info | | 03 Jul 2023 | 03 Jul 2023 | 03 Jul 2023 |
| Machine Age | HR | Client Info | | 0 | 0 | 0 |
| Oil Age | HR | Client Info | | 0 | 0 | 0 |
| Oil Changed | | Client Info | | N/A | N/A | N/A |
| Sample Status | | | | | | |

| SAMPLE IMAGES | method | limit/base | current | history 1 | history 2 | |
|---------------|--------|------------|----------|-----------|-----------|--|
| Color | | | no image | no image | no image | |
| Bottom | | | no image | no image | no image | |



OIL ANALYSIS REPORT

GRAPHS





Certificate L2367

Laboratory Sample No. Lab Number

Test Package : TEST

15

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 03 Jul 2023

: Q0004H9U Diagnosed : 03 Jul 2023 Diagnostician : Wes Davis

Unique Number : 16000492

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC

T: (919)379-4102

F: (919)379-4050

US 27513

Contact: WCLS CARY NC