

OIL ANALYSIS REPORT

Sample Rating Trend



TAN Auto **AutoTAN-1-QC** Component Oil Fluid

{not provided} (--- GAL)

DIAGNOSIS

| | | | | | | | | | | | | | | | | | | | | | | | 1 | |
|---|----|----|----|----|-----|---|---|---|--|--|---|--|--|--|--|--|--|--|--|--|--|--|---|--|
| 1 | т. | г. | г. | Ε. | - 1 | 1 | 1 | 1 | | | 1 | | | | | | | | | | | | | |




n2023 Jun2023 Jul2023 Jul2023 Jul2023 Jul2023 Jul2023 Jul2023

| SAMPLE INFORM | IATION | method | limit/base | current | history1 | history2 |
|---------------|--------|-------------|------------|-------------|-------------|-------------|
| Sample Date | | Client Info | | 21 Jul 2023 | 21 Jul 2023 | 21 Jul 2023 |
| Machine Age | HR | Client Info | | 0 | 0 | 0 |
| Oil Age | HR | Client Info | | 0 | 0 | 0 |
| Oil Changed | | Client Info | | N/A | N/A | N/A |
| Sample Status | | | | | | |
| SAMPLE IMAGES | ; | method | limit/base | current | history1 | history2 |
| Color | | | | no image | no image | no image |
| Bottom | | | | no image | no image | no image |



OIL ANALYSIS REPORT



WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513 Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (919)379-4102 F: (919)379-4050

