


OIL ANALYSIS REPORT

Sample Rating Trend







TAN Auto Machine Id AutoTAN-2-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		18 Aug 2023	18 Aug 2023	17 Aug 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CAMPLE IMAGES		mathad	limit/bass	aller and	hiotomit	hiotomyO


SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image




OIL ANALYSIS REPORT

GRAPHS









Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 16010216 Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : Q0004I5H Diagnosed

: 21 Aug 2023 Diagnostician : Wes Davis

: 21 Aug 2023

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)379-4050